0004

File ACT/007/006

PLATEAU MINING COMPANY

A Subsidiary of Getty Mining Company
P.O. Drawer PMC Price, Utah 84501
Telephone (801) 637-2875

#13

RECEIVED
NOV 26 1982
DIVISION OF
OIL, GAS & MINING

November 23, 1982

JIM
DEC 02 1982

Jim Smith
DOGM
4241 State Office Bldg.
Salt Lake City, Utah 84114

Copy to Wayne & Ken, Lynn

RE: CORRECTION OF THE DISTURBANCE ASSOCIATED WITH U.P.& L.'S ACTIVITIES IN POWER LINE CONSTRUCTION ON PMC'S PERMIT AREA.

Responded 12-2-82

Dear Jim,

Since the meeting with Floyd Johnson (OSM) and yourself, and our subsequent discussion on the power line disturbance, the following actions have been implemented.

PMC asked Utah Power and Light of their intentions relative to the access route associated with the power line corridor on our permit area. (See attached letter).

In light of this letter and a meeting with Ron Devenish and Kimball R. Rasmussen of Utah Power and Light, PMC hired J.T.S. Enterprises, Inc. to drill seed the area. This was completed on November 20, 1982. Also, a large earthen and rock berm were implimented on both ends of the disturbance to exclude use by the public.

The approved B.L.M. seed list was utilized and the job was accomplished prior to this last snow storm. I feel that the small area of disturbance should revegetate with no additional effort on our part.

If you concur, I will consider the matter satisfied other than to monitor the revegetation effort to make sure it is successful. I appreciate your recommendations in handling this potentially awkward situation.

Sincerely,

PLATEAU MINING COMPANY

M. A. Coonrod
Environmental Coordinator

cc: B. Lauman
G. Young
F. Tucker

utah power & LIGHT COMPANY

SOUTHERN DIVISION

P.O. BOX 277
AMERICAN FORK, UTAH 84003
TELEPHONE 801-756-7611

November 19, 1982

Mr. Mel Coonrod
Plateau Mining Company
PO Box PMC
Price, UT 84501

Dear Mr. Coonrod:

This letter shall serve as a formal response to your inquiry concerning the reclamation of the access corridor under or near our recently constructed power line that serves your mine.

The line has a minimum serviceable life of 30 to 50 years. While Plateau Mining is its principal user, it is also intended for service to other potential and existing customers. So, we would like to maintain an access corridor to enable our linemen to service the line when necessary. The corridor can be reseeded with BLM-approved seeds (for the particular environment), but we ask you not to dig up or alter the corridor in any other way.

Thank you for your consideration of this matter.

Sincerely,

Kimball R. Rasmussen

Kimball R. Rasmussen
Engineer

KRR/sl

cc Ron Devenish