0053
DOGM/NOV-1

FILE ACT/007/006
#7

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS & MINING
1588 West North Temple
Salt Lake City, Utah 84116
Telephone: (801) 533-5771

NOTICE OF VIOLATION NO.N 83-4-7-3

From the STATE OF UTAH
To the Following Permittee or Operator:

NAME Plateau Mining Co.
MINE Sarpoint #1 + #2 ☐ SURFACE ☒ UNDERGROUND ☐ OTHER
CATEGORY OF OWNERSHIP: ☐ STATE ☐ FEDERAL ☐ FEE ☒ MIXED
OSM MINE NO. STATE PERMIT NO. ACT/007/006 MSHA I.D. NO.
COUNTY AND STATE Carbon County, Utah TELEPHONE
MAILING ADDRESS: P.O. ~~Box~~ Drawer PMC, Price, Ut 84501
DATE OF INSPECTION July 28, 19 83.
TIME OF INSPECTION: FROM 10:30 ☒ a.m. to 4:30 ☐ a.m.
☐ p.m. to ☒ p.m.
NAME OF OPERATOR (If other than permittee)
MAILING ADDRESS:

Under the authority of the Utah Coal Mining and Reclamation Act of 1979 (Sec. 40-10-1 et seq., Utah Code Annotated, 1953), the undersigned authorized representative of the Director and the Division of Oil, Gas & Mining has conducted an inspection of the above mine on the above date and has found violation(s) of the Act, the regulations or required permit condition(s) listed in the attachment(s). This Notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that cessation of mining is ☐ is not ☒ expressly or in practical effect required by this Notice. For this purpose "Mining" means extracting coal from the earth or a waste pile and transporting it within or from the minesite.

This Notice shall remain in effect until it expires as provided on the reverse or is modified, terminated or vacated by written notice of an authorized representative of the Director of the Division of Oil, Gas & Mining. The time for abatement may be extended by the authorized representative for good cause, if a request is made within a reasonable time before the end of the abatement period.

Date of Service Aug. 4, 1983 David Lof
SIGNATURE OF AUTHORIZED REPRESENTATIVE

Time of Service 2:00 ☐ a.m. ☒ p.m. DAVID LOF #4
NAME AND I. D. NO.

Person Servied with Notice Ben Grimes, Environmental Coordinator
PRINT NAME AND TITLE

Signature ISSUED FROM THE OFFICE

IMPORTANT — PLEASE READ REVERSE OF THIS PAGE

56 64 16

DEPARTMENT OF NATURAL RESOURCES - DIVISION OF OIL, GAS, AND MINING
1588 West North Temple - Salt Lake City, Utah 84116 - (801) 533-5771

STATE OF UTAH

Notice of Violation No. N 83-4-1-3

Violation No. 1 of 3

Nature of the Violation

FAILURE TO OPERATE IN ACCORDANCE WITH AN APPROVED PLAN.
FAILURE TO ADEQUATELY PROTECT STOCKPILED SUBSOIL FROM WATER EROSION.

Provision(s) of the Regulations, Act, or Permit Violated

UCA 40-10-22(1)(c)
UMC 771.19
UCA 40-10-17(2)(e)
UMC 817.23 (b)

Portion of the Operation to which Notice Applies

THE VALLEY-FILL SUBSOIL STOCKPILE

Remedial Action Required (including interim steps, if any)

STEP CONTOUR THE FACE OF THE STOCKPILE IN ACCORDANCE WITH THE APPROVED PLAN AND STIPULATION 6-14-82-6 (TLP) WHICH IS ATTACHED TO THE JUNE 15, 1982 APPROVAL OF THE REVISION TO THE REFUSE PILE EXTENSION PLAN

Time for Abatement (including time for interim steps, if any)

ONE WEEK FROM DATE OF RECEIPT OF THIS NOTICE

56 64 16

DEPARTMENT OF NATURAL RESOURCES - DIVISION OF OIL, GAS, AND MINING
1588 West North Temple - Salt Lake City, Utah 84116 - (801) 533-5771

STATE OF UTAH

Notice of Violation No. N 83-4-7-3

Violation No. 2 of 3

Nature of the Violation

FAILURE TO OPERATE IN ACCORDANCE WITH AN APPROVED MINE PLAN.
FAILURE TO CONSTRUCT AND MAINTAIN SEDIMENT CONTROL MEASURES IN SUCH A MANNER AS TO PREVENT, TO THE EXTENT POSSIBLE, ADDITIONAL CONTRIBUTIONS OF SEDIMENT TO STREAMFLOW OR TO RUNOFF OUTSIDE THE PERMIT AREA AND TO MINIMIZE EROSION TO THE EXTENT POSSIBLE

Provision(s) of the Regulations, Act, or Permit Violated

UMC 771.19
UCA 40-10-22 (1)(c)
UMC 817.45
UCA 40-10-18(2)(i)(ii)

Portion of the Operation to which Notice Applies

DIVERSION DITCH No. 9

Remedial Action Required (including interim steps, if any)

MAINTAIN DIVERSION IN ACCORDANCE WITH THE APPROVED MINE PLAN
IE. RIPRAP AND ENSURE THAT DIVERSION IS ADEQUATELY SIZED

Time for Abatement (including time for interim steps, if any)

ONE WEEK FROM DATE OF RECEIPT OF THIS NOTICE

56 64 16

DEPARTMENT OF NATURAL RESOURCES - DIVISION OF OIL, GAS, AND MINING
1588 West North Temple - Salt Lake City, Utah 84116 - (801) 533-5771

STATE OF UTAH

Notice of Violation No. N 83-4-7-3

Violation No. 3 of 3

Nature of the Violation

FAILURE TO OPERATE IN ACCORDANCE WITH AN APPROVED PLAN.
FAILURE TO PROVIDE A DISCHARGE STRUCTURE WHICH WOULD SAFELY PASS THE RUNOFF FROM A 25-YEAR, 24-HOUR PRECIPITATION EVENT.
FAILURE TO CONSTRUCT SEDIMENT CONTROL MEASURES TO PREVENT, TO THE EXTENT POSSIBLE, ADDITIONAL CONTRIBUTIONS OF SEDIMENT TO RUNOFF OUTSIDE THE PERMIT AREA AND MINIMIZE EROSION TO THE EXTENT POSSIBLE.

Provision(s) of the Regulations, Act, or Permit Violated

UCA 40-10-22(1)(c)
UMC 771.19
UMC 817.46 (i)
UMC 817.45

Portion of the Operation to which Notice Applies

THE "DETENTION BASIN" FOR THE VALLEY-FILL SUBSOIL STOCKPILE

Remedial Action Required (including interim steps, if any)

INSTALL THE 18" CMP, DOWNSPOUT, AND ASSOCIATED RIPRAP SPLASH BASIN IN ACCORDANCE WITH THE APPROVED MINE PLAN.

Time for Abatement (including time for interim steps, if any)

ONE WEEK FROM DATE OF RECEIPT OF THIS NOTICE