

Note : Spring locations are approximate

RECEIVED
MAR 27 1986
DIVISION OF
OIL, GAS & MINING

LEGEND

- Surface Cracks
- Area where pillars have been pulled
- Identified seeps and springs
- Groundwater monitoring site

PREPARED BY
KUCERA & ASSOCIATES, INC.
Photogrammetric Consultants
Mentor, Ohio
Lakeland, Fla. Denver, Col.
Atlanta, Ga.

3	2	1	
4	5	6	
9	8	7	
10	11	12	

SHEET INDEX

NORTH

DATE OF PHOTOGRAPHY NOVEMBER 21-22, 1976

DESIGNED	DRAFTED	CHECKED
SCALE 1" = 400'	DATE	

REV.	DATE	DESCRIPTION	APPR.
1	12-81		JVH
2	7/83	Mining in 1983	
3	1/85	Mining in 1984	
4	1/86	Mining 1985	
5			
6			

SHEET 1 OF 4

PLATE 12-2

IDENTIFIED SURFACE SUBSIDENCE EFFECTS WITHIN THE PLATEAU MINE PLAN AREA

PLATEAU MINING CO.

P.O. BOX PMC PRICE, UTAH 84501 PHONE 801 637-2875

SHEET NO. 8