0011

Document Information Form

Mine Number: C/007/006

File Name: Incoming

To: DOGM

From:

Person N/A

Company OFFICE OF SURFACE MINING RECLAMATION AND ENFORCEMENT.

Date Sent: OCTOBER 03, 1988

Explanation:

TEN-DAY NOTICE.

cc:

File in:
C/ 007 , 006 , Incoming
Refer to:
- ☐ **Confidential**
- ☐ **Shelf**
- ☐ **Expandable**

Date _____ For additional information

RECEIVED
OCT 03 1988
DIVISION OF OIL, GAS & MINING

UNITED STATES DEPARTMENT OF THE INTERIOR
Office of Surface Mining
Reclamation and Enforcement

TEN-DAY NOTICE

Number: X - 88 - 02 - 107 - 9 TV 1

Originating Office: Albuquerque Field Office
625 Silver SW
Albuquerque NM 87102
Telephone Number: 505-766-1486

Ten-Day Notice to the State of Utah, Division of Oil, Gas + Mining

You are notified that, as a result of a Federal oversight inspection [illegible] information [illegible] the Operator has reason to believe that the person [illegible] violation [illegible] the Act. If the State Regulatory Authority [illegible] action to cause the violation(s) [illegible] transmit notice of your action [illegible] Federal inspection of the surface [illegible] be conducted and appropriate [illegible] taken.

Orig: Mine file #5
cc: Braxton
Whitehead
May
PFO

CERTIFIED
P 949 025 770
MAIL
OCT 1988

Permittee: Cyprus-Plateau Mining
(Or Operator if No Permit)
County: Carbon
Mailing Address: P.O. Drawer PMC Price, Utah 84501
Permit Number: ACT 007/006
Mine Name: Star Point

☐ Surface
☒ Underground
☐ Other

NATURE OF VIOLATION AND LOCATION: Failure to divert all surface drainage from the area above the coal processing waste and from the crest and face of the waste in accordance

Section of ~~State Law, Regulation or Permit Condition~~ believed to have ~~been violated~~:

~~NATURE OF VIOLATION AND LOCATION~~: with the requirements of the regulations; Failure to divert surface water from the area above the fill through diversion channels designed to pass

Section of State Law, Regulation or Permit Condition believed to have been violated: UMC 817.83 UMC 817.72(d)

~~NATURE OF VIOLATION AND LOCATION~~: safely the runoff from the 100yr 24 hr pr-c

File in:
☐ Confidential
☐ Shelf
☐ Expandable
Refer to Record No 0011 Date
In C/ 007 , 006 , Incoming
For additional information

ermit UMC 817-83
ed: UMC 817-72(d)

Remarks or Recommendations: Di [illegible] for both undisturbed and [illegible] area drainage should ~~[illegible]~~ address the 100yr 24hr criterion

Date of Notice: 9-29-88
Cert # P 949 025 770

Signature of Authorized Rep.: Rade H. Orell
Print Name and ID: Rade H. Orell

Distribution: Original-State's Copy, Blue-Field Office, Yellow-Inspector's Copy

IE-160 (3/81)

RECEIVED
OCT 03 1988
DIVISION OF
OIL, GAS & MINING

UNITED STATES DEPARTMENT OF THE INTERIOR
Office of Surface Mining
Reclamation and Enforcement

TEN-DAY NOTICE

Number: X - 88 - 02 - 107 - 9 TV 1

Originating Office: Albuquerque Field Office
625 Silver SW
Albuquerque NM 87102

Telephone Number: 505-766-1486

Ten-Day Notice to the State of Utah, Division of Oil, Gas + Mining

You are notified that, as a result of a Federal oversight inspection [illegible] ...ason to believe that the person [illegible] ...e Act. If the State Regulatory Authority [illegible] ... action to cause the violation(s) [illegible] ...transmit notice of your action to the Secretary through the [illegible] ...ederal inspection of the surface coal mining operation or [illegible] ... be conducted and appropriate [illegible] ...aken.

Orig: Mine file #5
cc: Braxton
Whitehead
May
PFO

CERTIFIED
P 949 025 770
PM
MAP

Permittee: Cyprus-Plateau Minings
(Or Operator if No Permit)

County: Carbon

Mailing Address: P.O. Drawer PMC Price, Utah 84501

Permit Number: Act 007/006

Mine Name: Star Point

☐ Surface
☒ Underground
☐ Other

NATURE OF VIOLATION AND LOCATION: Failure to divert all surface drainage from the area above the coal processing waste and from the crest and face of the waste in accordance

~~Section of State Law, Regulation or Permit Condition believed to have been violated:~~

~~NATURE OF VIOLATION AND LOCATION:~~ with the requirements of the regulations; failure to divert surface water from the area above the fill through diversion channels designed to pass

Section of State Law, Regulation or Permit Condition believed to have been violated: UMC 817.83 UMC 817.72(d)

~~NATURE OF VIOLATION AND LOCATION:~~ safely the runoff from the 100yr 24 hr precipitation event.

Section of State Law, Regulation or Permit Condition believed to have been violated: UMC 817-83 UMC 817-72(d)

Remarks or Recommendations: Diversion ditch design for both undisturbed and disturbed area drainage should ~~[illegible]~~ address the 100yr 24hr criteria

Date of Notice: 9-29-88
Cert # P 949 025 770

Signature of Authorized Rep.: Rade H. Orell

Print Name and ID: Rade H. Orell

Distribution: Original-State's Copy, Blue-Field Office, Yellow-Inspector's Copy

IE-160 (3/81)

RECEIVED
OCT 03 1988
DIVISION OF
OIL, GAS & MINING

UNITED STATES DEPARTMENT OF THE INTERIOR
Office of Surface Mining
Reclamation and Enforcement

TEN-DAY NOTICE

Number: X - 88 - 02 - 107 - 9 TV 1

Originating Office: Albuquerque Field Office
625 Silver SW
Albuquerque NM 87102
Telephone Number: 505-766-1486

Ten-Day Notice to the State of Utah, Division of Oil, Gas + Mining

You are notified that, as a result of a Federal oversight inspection [illegible] reason to believe that the person [illegible] the Act. If the State Regulatory [illegible] action to cause the violation(s [illegible] transmit notice of your action [illegible] federal inspection of the surface [illegible] be conducted and appropriate [illegible] taken.

Orig: Mine File #5
cc: Braxton
Whitehead
Mary
PFO

P 949 025 770

Permittee: Cyprus-Plateau Minings
(Or Operator if No Permit)
County: Carbon
Mailing Address: P.O. Drawer PMC Price, Utah 84501
Permit Number: ACT 007/006
Mine Name: Star Point

☐ Surface
☒ Underground
☐ Other

NATURE OF VIOLATION AND LOCATION: Failure to divert all surface drainage from the area above the coal processing waste and from the crest and face of the waste in accordance

Section of State Law, Regulation or Permit Condition believed to have been violated:

~~NATURE OF VIOLATION AND LOCATION~~: with the requirements of the regulations; Failure to divert surface water from the area above the fill through diversion channels designed to pass

Section of State Law, Regulation or Permit Condition believed to have been violated: UMC 817.83 UMC 817.72(d)

~~NATURE OF VIOLATION AND LOCATION~~: safely the runoff from the 100yr 24hr precipitation event.

Section of State Law, Regulation or Permit Condition believed to have been violated: UMC 817.83 UMC 817.72(d)

Remarks or Recommendations: Diversion ditch design for both undisturbed and disturbed area drainage should ~~safely p~~ address the 100yr 24hr criterion

Date of Notice: 9-29-88
Cert # P 949 025 770

Signature of Authorized Rep.: Rade H. Orell
Print Name and ID: Rade H. Orell

Distribution: Original-State's Copy, Blue-Field Office, Yellow-Inspector's Copy

IE-160 (3/81)