10-28-88 7125 0006

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/006
Inspection Date 10/20/88

Permittee/Operator Name Cyprus-Plateau Mining Co.
Business Address P.O. Drawer PMC
City Price State Ut Zip 84501
Mine Star Point ☐ Surface ☒ Underground ☐ Other
County Carbon State Ut.
Company Official(s) Ben Grimes
State Official(s) Bill Malencak & Henry Sauer
Time of inspection 9:00 ☒ a.m. ☐ p.m. to 1:00 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete
Date of last inspection 9/27-28/88 Weather conditions Clear/Warm/Dry Mine Site
Acreage 7200 52 ☐ Permitted 221 65 ☐ Disturbed ☐ Regraded ☐ Seeded 221 65 ☐ Bonded
Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☒
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. A07/007/006

Inspection Date 10/20/86

Please number comments to correspond with topics on previous page.

General Comments The purpose of this inspection was two fold (1) Followup on NOV-88-26-15-3 and (2) perform a partial inspection

Permit Mr Grimes stated that the small area near the coal silo that does not report to a sediment pond was included in the orginal permit and associated documents. A copy of these documents have been sent to the Price Office. However he also stated that he could not find in the renewal and more specifically in the MRP mention of approved small area exemptions. He said they had requested that small area exemptions be addressed at mid term. I advised Mr Grimes that this appears to be a permit defect and I would get back with him on the time frame for corrective action. As part of the NOV my abatement time frame is limited by state regulations to 90 days. Double straw bales have been installed in four small drainage areas. The area where equipment was utilized to construct the sediment control measures will be seeded this fall with an approval seed mix.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. _____

Inspection Date _____

Please number comments to correspond with topics on previous page.

The straw bales and other sediment control measures were installed on October 10, 1988 according to the operator. The runoff catchments above the straw bales caught water. The last storm of record was October ~~12~~ 13. [illegible]

The operator took remedial action ie,

(1) Provided documentation that DOGM has granted the operator a small area exemption and

(2) Provided sediment control.

As related to item (1) above documentation was provided, but it does not tie in with the current permit or MRP. I advised the operator that the matter will have to be discussed with DOGM management and it would seem the operator should be provided a reasonable time to correct the current permit/MRP defect.

As related to item (2) the work has been completed and approved. This subpart of the aforementioned NOV violation 1 of 3 is terminated. The other subpart relating to approval of the small area exemption is still pending.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. _____

Inspection Date _____

Please number comments to correspond with topics on previous page.

Diversions: The "Munson Culvert work" has been completed. Culvert 60A & 61A are in the final stages of completion. The balance have been previously completed and covered in a prior inspection

Sediment Ponds. Sediment ponds 4, 5, & 6 were checked and no problems noted.

Erosion control and runoff control work has been completed. The aforementioned NOV, violation 3 of 3 is terminated

Coal Processing Waste. The aforementioned NOV, violation 2 of 3 was vacated. This matter is currently under consideration by the operator as to whether or not a piezometer will be installed as a replacement to the piezometer that was covered by the Price River Coal that was placed on Cyprus Plateau refuse area.

Copy of report mailed to SLC For: OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report given to Ben Grimes

Inspector's signature [signature] No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

10/20/88

DOGM/IR-2

an equal opportunity employer

11/86 001049