12-21-89 7/12

0001

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/006

Inspection Date 12/5/89

Permittee/Operator Name Cyprus Plateau Mining Co.

Business Address P.O. Drawer P.MC

City Price State Ut Zip 84501

Mine Starpoint ☐ Surface ☒ Underground ☐ Other

County Carbon State Ut

Company Official(s) Ben Grymes

State Official(s) Bill Malencik --- Mitch Rollinger - OSM

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 4:30 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection _____ Weather conditions Clear/Cool/Some Snow On Mtns.

Acreage 7200 ☐ Permitted 221 ☐ Disturbed ☐ Regraded ☐ Seeded 221 ☐ Bonded

Enforcement Action NOV. 89-26-22-2

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☒	☐	☒
— Other sediment control measures	☒	☒	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☒	☐	☐	☐
5. Explosives	☒	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
— Construction	☒	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☒	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date 12/5/89

Please number comments to correspond with topics on previous page.

General Comments. This oversight inspection was performed by the undersigned with Mitch Rollings, OSM conducting the oversight. The last complete inspection was performed by Tom Munson, SLC, Oct 11, 1989. Since July 1989 this mine was assigned to Bill Warmack, who has recently resigned from the Division.

Permit. Division approved five year renewal on August 7, 1987 with OSM concurrence on January 17, 1989.

- NPDES Permit UT-0023736 was on file at the mine office and approved by Ut. State Health Dept on 1/22
- Other records as required were in order.

Sediment Ponds. The mine sediment ponds were checked. Also three disturbed areas were observed that do not drain into the ponds. The areas are as follows:

- Upper Pad - disturbed drainages that discharges to a sediment trap S-11, thence through a culvert under the paved road and into an undisturbed drainage
- Upper Pad - explosive storage area that drains across a pad through a silt fence, thence a downspout and into the undisturbed drainage

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date 12/5/89.

Please number comments to correspond with topics on previous page.

• Middle Area - disturbed area north of alternative sediment control area #1 that does not have total sediment control that drains into an undisturbed drainage

Diversions Two culvert outlets were pointed out to the operator as a maintenance problem. Suggested that the outlets be rip rapped.

Other Sediment Control, a NOV 89-26-22-2 (1 of 2) was issued for failure to pass these disturbed areas through a sediment pond. The abatement measure is to submit plans/map and implement approved sediment control measures. The areas will thereafter be classified as ~~Small~~ Alternative Sediment Control Areas and exempt from draining into a pond.

Also atoumention NOV part 2 of 2 was issued for failure minimize erosion to extent possible on an unprotected outslope south of the old tipple.

Copy of report mailed to Plateau/Ben Grimes SLC: For OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed RFO

Inspector's signature Tim J. Drahnick No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

12/14/89.

DOGM/IR-2

an equal opportunity employer

11/86 001049