0009

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gph RVS



# inspection report

Permit No. ACT/007/006
Inspection Date 8/21/89

Permittee/Operator Name Cyprus-Plateau Mining Company
Business Address PO Drawer PMC
City Price State UT Zip 84501
Mine Starpoint ☐ Surface ☒ Underground ☐ Other
County Carbon State UT
Company Official(s) Steve Jones
State Official(s) Darin Worden and Tom Munson
Time of inspection 8:30 ☒ a.m. ☐ p.m. to 11:00 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete
Date of last inspection July, 28, 1989 Weather conditions Sunny - Warm
Acreage 7200 ☒ Permitted 221.65 ☒ Disturbed ☐ Regraded ☐ Seeded 221.65 ☒ Bonded
Enforcement Action None

## COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | YES | NO | N/A | COMMENTS |
|---|---|---|---|---|
| 1. Permits | ☐ | ☐ | ☐ | ☐ |
| 2. Signs and markers | ☐ | ☐ | ☐ | ☐ |
| 3. Topsoil | ☒ | ☐ | ☐ | ☐ |
| 4. Hydrologic balance | | | | |
| a – Stream channel diversions | ☐ | ☐ | ☐ | ☐ |
| b – Diversions | ☒ | ☐ | ☐ | ☒ |
| c – Sediment ponds and impoundments | ☐ | ☐ | ☐ | ☐ |
| d – Other sediment control measures | ☐ | ☐ | ☐ | ☐ |
| e – Surface and groundwater monitoring | ☐ | ☐ | ☐ | ☐ |
| f – Effluent limitations | ☐ | ☐ | ☐ | ☐ |
| 5. Explosives | ☐ | ☐ | ☐ | ☐ |
| 6. Development waste and spoil disposal | ☐ | ☐ | ☐ | ☐ |
| 7. Coal processing waste | ☒ | ☐ | ☐ | ☐ |
| 8. Noncoal waste | ☐ | ☐ | ☐ | ☐ |
| 9. Protection of fish, wildlife, and related environmental values | ☐ | ☐ | ☐ | ☐ |
| 10. Slides and other damage | ☐ | ☐ | ☐ | ☐ |
| 11. Contemporaneous reclamation | ☒ | ☐ | ☐ | ☒ |
| 12. Backfilling and grading | ☐ | ☐ | ☐ | ☐ |
| 13. Revegetation | ☐ | ☐ | ☐ | ☐ |
| 14. Subsidence control | ☐ | ☐ | ☐ | ☐ |
| 15. Cessation of operations | ☐ | ☐ | ☐ | ☐ |
| 16. Roads | | | | |
| – Construction | ☐ | ☐ | ☐ | ☐ |
| – Drainage controls | ☐ | ☐ | ☐ | ☐ |
| – Surfacing | ☐ | ☐ | ☐ | ☐ |
| – Maintenance | ☐ | ☐ | ☐ | ☐ |
| 17. Other transportation facilities | ☐ | ☐ | ☐ | ☐ |
| 18. Support facilities and utility installations | ☐ | ☐ | ☐ | ☐ |

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Page ___ of ___

## INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date 8/21/89

Please number comments to correspond with topics on previous page.

4)6) Diversion 76 was inspected for as-built conditions. The operator was in the process of installing rip rap at the ditches outlet. All looked good.

6B Diversion has recently been completed. Since that time several precipitation events have occured which caused the ditch to convey water. The lower end of the ditch was nearly ~~stilled~~ silted in and the inlet to the culvert was plugged. The operator cleared the inlet before the inspection was complete. The operator also committed to restore channel capacities prior to the culverts inlet no later than August 28, 1989, and to install 2 sediment traps in the ditch prior to the culvert inlet.

11) The SAE topsoil pile was inspected. Some evidence of gully erosion was apparent on the lower portions of the pile. No gullies were 9" deep or greater.

Copy of report mailed to Ben Grimes (C-DMC); Brian Smith (OSM; Bill Wormack (PFO)

Copy of report given to Rick Smith (DOGM)

Inspector's signature Darin Worden No. ___

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049