7125 0010

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

RJS

inspection report

Permit No. ACT/007/006

Inspection Date July 28, 1989

Permittee/Operator Name Cyprus-Plateau Mining Co.

Business Address P.O. Drawer PMC

City Price State UT Zip 84501

Mine Starpoint ☐ Surface ☒ Underground ☐ Other

County Carbon State UT

Company Official(s) Steve Jones

State Official(s) Bill Warmack

Time of inspection 8:30 ☒ a.m. ☐ p.m. to 11:30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection June 30, 1989 Weather conditions partly cloudy

Acreage 7200 ☒ Permitted 221.65 ☒ Disturbed ☐ Regraded ☐ Seeded 221.65 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a. Stream channel diversions	☐	☐	☐	☐
b. Diversions	☒	☐	☐	☐
c. Sediment ponds and impoundments	☒	☐	☐	☒
d. Other sediment control measures	☒	☐	☐	☒
e. Surface and groundwater monitoring	☒	☐	☐	☒
f. Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐

	YES	NO	N/A	COMMENTS
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a. Construction	☐	☐	☐	☐
b. Drainage controls	☒	☐	☐	☐
c. Surfacing	☐	☐	☐	☐
d. Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No ACT/007/006

Inspection Date July 28, 1989

Please number comments to correspond with topics on previous page.

GENERAL: Mr. Steve Jones (C-PMC) accompanied the undersigned during this partial inspection. Afternoon rain showers on 7/27/89 produced runoff in isolated areas throughout the site.

4c. Sed Ponds: Ponds 1, 2, 3, 6, 7, & 9 contained water; Pond 5 was dry. All ponds appeared stable & in good repair.

4d. Other Sed Controls: Silt fence/straw bales near the non-coal waste storage area appeared to be functioning properly. Water & sediment were contained by the structure. Several sediment basins contained water & did not show any evidence of discharge.

4e. Surface & Groundwater Monitoring: Water flow measurements were taken in U-North 2ND & 3RD East. Data is being utilized to determine the effects of subsidence upon Miller Creek.

Copy of report mailed to SLC GO: Joe Helfrich (DOGM), Brian Smith (OSM) Ben Grimes (C-PMC)

Copy of report given to PFO

Inspector's signature William A. Wermack 7/28/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE