0015

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/006

Inspection Date 6/13/90

Permittee/Operator Name Cyprus Plateau Mining Co.

Business Address P.O. Drawer PMC

City Price State Ut Zip 84501

Mine Starpoint ☐ Surface ☐ Underground ☐ Other

County Carbon State Ut

Company Official(s) Steve Jones & Mike Kelley.

State Official(s) Bill Malencik

Time of inspection 1:00 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 5/11/90 Weather conditions Clear/Warm.

Acreage 7200 ☐ Permitted 221 ☐ Disturbed ☐ Regraded ☐ Seeded 221 ☐ Bonded

Enforcement Action None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☒	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date 6/13/90

Please number comments to correspond with topics on previous page.

General Comments: This partial inspection concentrated on exemption areas and treatment relating thereto. Also, dimensions were checked where silt fences had been installed adjacent to the refuse pile.

Dimensions

- Ditch 9A above the old tipple that is riprapped and grouted had the berm height increased as suggested in the report of 4/13/90.
- Berms around the powder and cap magazine had been beefed up.
- Ditch 8 on the back side of the refuse pile was fully function. The operator was replacing some silt fences in the ditches

Exemption Area: The area above the subsoil pile that does not drain into a sediment pond, was previously treated with straw bales, and is currently being treated with sediment traps.

Sediment Ponds: Sediment ponds 1, 2, 8 & 9 were observed and no problems noted

CPCMC: Ben Grimes

Copy of report mailed to SLC: OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report given to RFO

Inspector's signature Jim J. Smalenick No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

6/19/90

DOGM/IR-2

an equal opportunity employer

11/86 001049