0011

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gch pgl

inspection report

Permit No. ACT/007/006

Inspection Date 10/20/91

Permittee/Operator Name CYPRUS PLATEAU MINING COMPANY

Business Address P.O. DRAWER PMC

City PRICE State UT Zip 84501

Mine STAR POINT ☐ Surface ☒ Underground ☐ Other

County CARBON State UT

Company Official(s) BEN GRIMES

State Official(s) TOM MUNSON

Time of inspection 1:00 ☐ a.m. ☑ p.m. to 3:00 ☐ a.m. ☑ p.m. ☒ Partial ☐ Complete

Date of last inspection 10/4/91 Weather conditions

Acreage 7200 ☒ Permitted 221 ☒ Disturbed ☐ Regraded ☐ Seeded 221 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☑	☐	☐	☑
c Sediment ponds and impoundments	☑	☐	☐	☑
d Other sediment control measures	☐	☐	☐	☐
e Surface and groundwater monitoring	☑	☐	☐	☑
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date 11/21/91

Please number comments to correspond with topics on previous page.

4b Diversions - All diversions appeared cleared surrounding the refuse pile. The diversion taking water off the pile needed maintenance and was maintained while we were on site. It is a constant maintenance issue as the refuse pile is a dynamic affair constantly changing. All dozer operators must be made aware of the diversion and its purpose.

4c Sediment ponds and impoundments -
Pond #8 by the loadout had been cleaned and was in good shape. The other ponds will be revamped once the division reviews and approves plans to modify all ponds and impoundments to come into compliance with the new rules.

4e Surface and Groundwater Monitoring -
The data for the third quarter was submitted

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date

Please number comments to correspond with topics on previous page.

to the division on November 7, 1991 and the results of this sampling period have been verified regarding frequency and parameters sampled both at the mine and at the division.

Copy of report mailed to BENGRIMES (PMC), Bernie Freeman (Alb.)

Copy of report given to JOE HELFRICH (DOGM)

Inspector's signature Tom Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE