0020

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gh pgl

inspection report

Permit No. ACT/007/006

Inspection Date 8/29/91

Permittee/Operator Name Cyprus Plateau Mining Corporation

Business Address P.O. Drawer PMC

City Price State Utah Zip 84501

Mine Starpoint ☐ Surface ☒ Underground ☐ Other

County Carbon State Utah

Company Official(s) Ben Grimes, John Borla

State Official(s) Jess Kelley

Time of inspection 9:30 ☒ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 7/30/91 Weather conditions Clear and warm

Acreage 7200 ☒ Permitted 221 ☒ Disturbed ☐ Regraded ☐ Seeded 221 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☒	☐	☐	☒
c Surfacing	☐	☐	☐	☐
d Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date 8/29/91

Please number comments to correspond with topics on previous page.

4. HYDROLOGIC BALANCE

(c) Sediment Ponds and Impoundments-- Sediment ponds all contained some water. All were in good condition. Sediment traps were also in good condition, despite heavy recent rainfall. Sediment trap S7, which lies north of and across the main road from Pond 9, has reached its maximum sediment capacity and is scheduled for cleaning during September.

(d) Other Sediment Control Measures-- The new refuse pile drainage system (Amendment 91B) is awaiting the arrival of 30" CMP for completion. The berm at the top of the refuse pile, which was built as part of this system, is in good repair.

16. ROADS

(b) Drainage Controlls-- All roadside ditches and sediment traps are in good repair and free from debris and other obstructions.

Copy of report mailed to Ben Grimes (Cyprus Plateau); John Kathman (OSM)

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature Gene W. Kelley No. 34

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE