0024

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/006

Inspection Date 6/27/91

Permittee/Operator Name CYPRUS-PLATEAU MINING CORP.

Business Address P.O. DRAWER PMC

City PRICE State UTAH Zip 84501

Mine STAR POINT ☐ Surface ☒ Underground ☐ Other

County CARBON State UTAH

Company Official(s) ROBERT ROLLEY

State Official(s) Tom MUNSON

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 2:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection 5/22/91 Weather conditions SUNNY

Acreage 7200 ☐ Permitted 221 ☐ Disturbed ☐ Regraded ☐ Seeded 221 ☐ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
b — Diversions	☒	☐	☐	☒
c — Sediment ponds and impoundments	☒	☐	☐	☒
d — Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☒
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date 6/27/91

Please number comments to correspond with topics on previous page.

1. Permits - All permits, [redacted] insurance, and bonding documents were in order and up to date.

4b Diversions - All diversions and trash racks were inspected and found to be ucently maintained. Inlets previously blocked with debris on the last complete inspections were clean and found to be in good working order.

4c. Sediment Ponds - Sediment Pond inspections were last completed on March 27, 1991 and 2ND Quarter inspections have not been completed and are not due until June 30, 1991. No discharges were noted since the last inspection.

4d. Other Sediment Control Measures - Silt fences were constructed along the

Copy of report mailed to

Copy of report given to

Inspector's signature Tom Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/006

Inspection Date 6/27/91

Please number comments to correspond with topics on previous page.

road ditches to the office bldg on the portal pad. The welded wire construction with the trapezodial overflow was well done.

7. Coal Processing Waste - The refuse pile was inspected ~~and the~~ on March 27, 1991 and the 2ND Quarter Inspection was not due until 6/30/91 and had not been completed by the inspection date.

A proposal to culvert runoff off the outslope of the refuse pile below the two working face is being approved by the Division. A memo is being generated to document this approval on 7/3/91.

Overall due to the miner's move of a longwall ~~[illegible]~~, the surface facilities maintance was impressive and no problem with ditch, culverts, inlets, sediment controls were found.

Copy of report mailed to Plateau Bill Brines; OSM Brian Smith

Copy of report given to Joe Helfrich / DOG

Inspector's signature Tom Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE