0031

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. Act 007/006

Inspection Date Feb. 10, 1993

Permittee/Operator Name Cyprus Plateau Mining Corp

Business Address P.O. Drawer PCMC

City Price State Ut Zip 84501

Mine Star Point ☐ Surface ☒ Underground ☐ Other

County Carbon State Ut

Company Official(s) Peter Nelson

State Official(s) Bill Malencik

Time of inspection 10:00 ☒ a.m. ☐ p.m. to 3:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 1/6&7/93 Weather conditions Snow/Cloudy

Acreage 7200 ☐ Permitted 221 ☐ Disturbed ☐ Regraded ☐ Seeded 221 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☒	☐	☐	☒
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act 007/006

Inspection Date 2/10/93

Please number comments to correspond with topics on previous page.

General Comments. Areas covered in the partial inspection included the upper pad, tipple area, refuse pile, and silo area. Areas not covered included the back side of the refuse pile and the number one mine and roads going to same. Measured 40" of packed snow on the upper pad storage area. The mine had received about four inches of snow the night before the inspection.

Topsoil. Soil material had been removed from the amended road prosect. The material was stored in an existing soil stockpile adjacent to the road prosect underway. The topsoil pile has been protected by a berm constructed adjacent to the pile. The pile must be seeded with an interim seed mix.

Sediment Ponds. Ponds 2, 3, 4, 7 & 8 were observed. All were snow covered and pond 8 & 9 were about 1/4 of runoff capacity. The others did not have a significant amount of runoff.

Roads. The road prosect is completed with the exception of blacktopping the surface. The permit supervisor advised the operator of four followup items that will have to be completed when the road has given its final surfacing.

Copy of report mailed to CPMC/Pat Nelson, OSM/Brian Smith, DOGM/Joe Helfrich

Copy of report ~~given~~ filed to PFO

Inspector's signature Tom J. Malencik No. 76

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

2/26/93.