0028

Route & File
COPY ACT/007/007
To Joe, first
JWS

United States Department of the Interior
OFFICE OF SURFACE MINING
Reclamation and Enforcement
BROOKS TOWERS
1020 15TH STREET
DENVER, COLORADO 80202

July 1, 1980

Mr. Ron Daniels
Coordinator of Mined Land Development
Department of Natural Resources
1588 West North Temple
Salt Lake City, Utah 84116

Dear Mr. Daniels:

Enclosed please find copies of **Notice of Violation 80-5-7-16** which were issued to mining companies within your State during this offices recent on-site inspections conducted on **June 24, 1980.**
If you have any questions or problems, please contact this office.

Mine inspection reports for all of the operations inspected during the above time frame, and within your State, will be sent to you as soon as they are processed.

Sincerely,

Thomas E. Ehmett, Acting Chief
Division of Inspection & Enforcement

RECEIVED
JUL 03 1980
DIVISION OF
OIL, GAS & MINING

OSM 722-1
Revised 4/30/79

N ~~500611~~

UNITED STATES DEPARTMENT OF THE INTERIOR
OFFICE OF SURFACE MINING RECLAMATION AND ENFORCEMENT

Region V
1823 Stout Street
Denver, Colorado 80202
Telephone: (303) 837-5511
(303) 837-5701

RECEIVED
JUL 03 1980
DIVISION OF
OIL, GAS & MINING

NOTICE OF VIOLATION NO. N 80-5-7-16 TV

To the Following Permittee or Operator:

Name Kaiser Steel Corporation

Mine Sunnyside ☐ Surface ☒ Underground ☐ Other

County and State Carbon, Utah Telephone 801-888-4421

Mailing Address P.O. Box D Sunnyside, Utah 84539

OSM Mine No. — State Permit No. ACT/007/007 MSHA I.D. No. 42-0094

Date of Inspection 24 June, 19 80

Time of Inspection: from 10:30 ☒ a.m. to 7 ☐ a.m.
☐ p.m. to ☒ p.m.

Name of Operator (if other than permittee)

Mailing Address

Under the authority of the Surface Mining Control and Reclamation Act of 1977 (P.L. 95-87; 30 U.S.C. 1201), the undersigned authorized representative of the Secretary of the Interior has conducted an inspection of the above mine on the above date and has found violation(s) of the Act, the regulations or required permit condition(s) listed in the attachment(s). This Notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned authorized representative finds that cessation of mining is ☐ is not ☒ expressly or in practical effect required by this Notice. For this purpose "mining" means extracting coal from the earth or a waste pile and transporting it within or from the minesite.

This Notice shall remain in effect until it expires as provided on the reverse or is modified, terminated, or vacated by written notice of an authorized representative of the Secretary. The time for abatement may be extended by an authorized representative for good cause, if a request is made within a reasonable time before the end of the abatement period.

Date of Service 30 June 1980

Eileen M. Doherty
Signature of Authorized Representative

Time of Service 4:30 ☐ a.m. ☒ p.m.

E.M. Doherty V-17
Name and I.D. No.

Person Served with Notice John Huefner - P.R. Engineer
Print Name and Title

Signature Due to late hour, operator preferred a mailing. EMD

IMPORTANT – PLEASE READ REVERSE OF THIS PAGE

Permittee/Operator
~~STATE~~

OSM 722-1 A
Revised 4/30/79

Notice of Violation No. N 80-5-7-16

Violation No. 1 of 8

Nature of the Violation

Failure to maintain access road to protect streamflow.

Provision(s) of the Regulations, Act, or Permit Violated

30 CFR 717.17 (j) (1)
P.L. 95-87 Sec. 516 (b)

Portion of the Operation to which Notice Applies

Berms along access road to Man Shaft Area, above Grassy Trail Creek.

Remedial Action Required (including interim steps, if any)

Repair and maintain breached berms.

Time for Abatement (including time for interim steps, if any)

July 30, 1980.

PERMITTEE/OPERATOR

1970

OSM 722-1 A
Revised 4/30/79

Notice of Violation No. N 80-5-7-16

Violation No. 2 of 8.

Nature of the Violation

Failure to reclaim (grade) inactive surface work areas.

Provision(s) of the Regulations, Act, or Permit Violated

30 CFR 717.14 (a) general
P.L. 95-87 sec. 516 (b)

Portion of the Operation to which Notice Applies

Crossing on Grassy Trail Creek which provided access to Main Shaft area sediment pond construction site.

Remedial Action Required (including interim steps, if any)

Re-establish and stabilize affected banks of Grassy Trail Creek at crossing site. Regrade and reclaim.

Time for Abatement (including time for interim steps, if any)

July 30, 1980.

PERMITTEE/OPERATOR

19748

OSM 722-1 A
Revised 4/30/79

Notice of Violation No. N 80-5-7-16

Violation No. 3 of 8

Nature of the Violation

Failure to construct and maintain transport facilities to minimize effects on water quality and nature.

Provision(s) of the Regulations, Act, or Permit Violated

30 CFR 717.17 (K)
P.L. 95-87 Sec. 516 (b)

Portion of the Operation to which Notice Applies

Man and coal transport bridge over Grassy Trail Creek at the main mine entry.

Remedial Action Required (including interim steps, if any)

Prevent coal spillage from bridge into Creek.

Time for Abatement (including time for interim steps, if any)

August 29, 1980.

PERMITTEE/OPERATOR

1971

OSM 722-1 A
Revised 4/30/79

Notice of Violation No. N 80-5-7-16

Violation No. 4 of 8.

Nature of the Violation

Operating without a permit

Provision(s) of the Regulations, Act, or Permit Violated

30 CFR 710.11 (a) (3)
30 CFR 717.11 (a)
P.L. 95-87 Sec. 502 (a)

Portion of the Operation to which Notice Applies

The three borrow pits used as sources of fill and cover material. These pits are located adjacent to the slurry pond and the coarse refuse pile.

Remedial Action Required (including interim steps, if any)

Apply for approval to use these areas, and any other anticipated areas, as "borrow pits". Apply to the Utah Division of Oil, Gas, & Mining, and the Denver Office of Surface Mining for a permit modification.

Time for Abatement (including time for interim steps, if any)

July 30, 1980

PERMITTEE/OPERATOR

19772

OSM 722-1 A
Revised 4/30/79

Notice of Violation No. N 80-5-7-16

Violation No. 5 of 8.

Nature of the Violation

Failure to protect undisturbed overland flow from disturbed areas.

Provision(s) of the Regulations, Act, or Permit Violated

30 CFR 717.17 general
30 CFR 717.17 (c) general
P.L. 95-87 sec. 516 (b)

Portion of the Operation to which Notice Applies

Slaughter Canyon Drainage which passes through portal site.

Remedial Action Required (including interim steps, if any)

Either:
Protect undisturbed runoff from disturbed area, as approved.
or: Pass all affected runoff thru sedimentation structure, as approved.

Time for Abatement (including time for interim steps, if any)

September 29, 1980

PERMITTEE/OPERATOR

19372

OSM 722-1 A
Revised 4/30/79

Notice of Violation No. N 80-5-7-16

Violation No. 6 of 8

Nature of the Violation

Failure to maintain access road to protect area hydrology.

Provision(s) of the Regulations, Act, or Permit Violated

30 CFR 717.17 (j) (1)
P.L. 95-87 Sec. 516 (b)

Portion of the Operation to which Notice Applies

Slaughter Canyon portal access road.

Remedial Action Required (including interim steps, if any)

Repair breached berms, and maintain road to prevent surface runoff from affected areas from entering channel.

Time for Abatement (including time for interim steps, if any)

September 29, 1980

PERMITTEE/OPERATOR

19786

OSM 722-1 A
Revised 4/30/79

Notice of Violation No. N 80-5-7-16

Violation No. 7 of 8

Nature of the Violation

Failure to pass surface runoff through a sedimentation control structure.

Provision(s) of the Regulations, Act, or Permit Violated

30 CFR 717.17 (a)
P.L. 95-87 sec. 516 (b)

Portion of the Operation to which Notice Applies

Slaughter Canyon portal site, and associated access road.

Remedial Action Required (including interim steps, if any)

Control surface runoff from cited areas, with Regulatory Authority approval.

Time for Abatement (including time for interim steps, if any)

September 29, 1980

PERMITTEE/OPERATOR

19755

OSM 722-1 A
Revised 4/30/79

Notice of Violation No. N 80-5-7-16

Violation No. 8 of 8

Nature of the Violation

Failure to obtain a Solid Waste Disposal Permit as required by the Utah Division of Health for the Industrial Waste Site on this mine.

Provision(s) of the Regulations, Act, or Permit Violated

30 CFR 710.11 (a) (2)
P.L. 95-87 Sec. 502 (a)

Portion of the Operation to which Notice Applies

Industrial Waste Site.

Remedial Action Required (including interim steps, if any)

Obtain Health Division approval for disposal as directed in February 1980 letter from Utah DOGM to Kaiser Steel.

Time for Abatement (including time for interim steps, if any)

July 14, 1980.

PERMITTEE/OPERATOR

19766