9-24-87 0008

File

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No ACT/007/007

Inspection Date Sept 11, 1987

Permittee/Operator Name Kaiser Coal Corporation

Business Address Post Office Box D.

City Sunnyside State Utah Zip 84539

Mine Sunnyside ☐ Surface ☒ Underground ☐ Other

County Carbon State Ut.

Company Official(s) Barry G Grosely

State Official(s) Bill Malencik, Harold Sandbeck

Time of inspection 9 00 ☒ a m ☐ p m to 4 00 ☐ a m ☒ p m ☒ Partial ☐ Complete

Date of last inspection August 11, 1987 Weather conditions Clear/Warm/Dry Site

Acreage 14.535 ☐ Permitted 287 ☐ Disturbed — ☐ Regraded — ☐ Seeded 287 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1 Permits	☐	☐	☐	☐
2 Signs and markers	☒	☐	☐	☒
3 Topsoil	☐	☐	☐	☐
4 Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5 Explosives	☐	☐	☒	☐
6 Development waste and spoil disposal	☐	☐	☒	☐
7 Coal processing waste	☐	☐	☐	☐
8 Noncoal waste	☐	☐	☐	☐
9 Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10 Slides and other damage	☐	☐	☒	☐
11 Contemporaneous reclamation	☐	☐	☐	☐
12 Backfilling and grading	☐	☐	☐	☐
13 Revegetation	☐	☐	☐	☐
14 Subsidence control	☐	☐	☐	☐
15 Cessation of operations	☐	☐	☒	☐
16 Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☒	☐	☐	☒
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17 Other transportation facilities	☐	☐	☒	☐
18 Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

Jck

INSPECTION REPORT COMMENTS

Permit No. ACT 007/007

Inspection Date 9/11/87

Please number comments to correspond with topics on previous page.

General Comments. The mine company was working on drainage and sediment control measures & structures. The repair work needed was mentioned in a previous inspection report of 8/11/87. The deadline date for the repair work was 9/30/87. It was premature to relook at these items

Signs & Markers. Required signs were observed on site. Some markers in No 2 Canyon need to be rechecked in order to assure that they will meet the "clearly marked" criterion in the regulations

Sediment Pond. The sediment ponds, 2 in number, adjacent to the storage pad did not contain water and required minor maintenance. These are located in No 2 Canyon.

Road Drainage Controls. The recent concrete culvert inlet & outlet protection in No 2 Canyon held up well in spite of the high intensity storm mentioned in the inspection report of 8/11/87. The road drainage ie, discharging into an undisturbed drainage may require additional considerations in order to assure effluent limitations are met.

Copy of report mailed to Barry G Grosely KCC; Brian Smith, OSM

Copy of report given to Joe Helfrich

Inspector's signature Tom J Chalmick No. 26

9/18/87

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2 an equal opportunity employer 11/86 001049

~~Sent~~ Mailed to Operator on 9/18/87 [illegible]