0013 RY 8-3-87 file

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No ACT/007/007

Inspection Date 7/17/87

Permittee/Operator Name Kaiser Coal Corp. (KCC)

Business Address P.O. Box D

City Sunnyside State UT Zip 84539

Mine Sunnyside Complex ☐ Surface ☒ Underground ☐ Other

County Carbon State

Company Official(s) Karl HouseKeeper & Barry Grosely

State Official(s) Jim Fricke & Bill Malencik

Time of inspection 9 00 ☒ a m ☐ p m to 3 00 ☐ a m ☒ p m ☒ Partial ☐ Complete

Date of last inspection 6/9/87 Weather conditions Windy 70°F

Acreage 14,535 ☒ Permitted 287.4 ☒ Disturbed ☐ Regraded ☐ Seeded 287.4 ☒ Bonded

Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1 Permits	☐	☐	☐	☐
2 Signs and markers	☒	☐	☐	☒
3 Topsoil	☐	☐	☐	☐
4 Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☒	☐	☐	☒
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☒	☐	☐	☐
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5 Explosives	☐	☐	☐	☐
6 Development waste and spoil disposal	☐	☐	☐	☐
7 Coal processing waste	☐	☐	☐	☐
8 Noncoal waste	☐	☐	☐	☐
9 Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10 Slides and other damage	☐	☐	☐	☐
11 Contemporaneous reclamation	☐	☐	☐	☐
12 Backfilling and grading	☐	☐	☐	☐
13 Revegetation	☐	☐	☐	☐
14 Subsidence control	☐	☐	☐	☐
15 Cessation of operations	☐	☐	☐	☐
16 Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☐	☐	☐	☐
c Surfacing	☐	☐	☐	☐
d Maintenance	☒	☐	☐	☒
17 Other transportation facilities	☐	☐	☐	☐
18 Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/007

Inspection Date 7/17/87

Please number comments to correspond with topics on previous page.

2. Permit area posts were noted in Whitmore Canyon, #2 Canyon, Old Coarse Refuse Haul Road and Icelander Wash. Spoil Pile and Topsoil signs were ~~noted~~ in place for the newly constructed Sunnyside Surface Facilities Pond (SSSF) and Coarse Refuse Toe Pond (CRT).

4b. Culverts RC3-1, RC3-2, C1, C3, C5, C8, C11, RC1-3, 1C, RC7-3, RC10-4, Old Haul Road, DA I + II were inspected for outlet erosion protection as part of a permit commitment, all outlet protection devices were installed and functional.

4c. Old Coarse Refuse Road pond was inspected, the pond was dry and has been for some time evidenced by the vegetation growth in the pond floor. The Upper #2 Canyon pond was inspected, the operator was asked to remove 2 Longwall panels ~~th~~ from the inlet, the inlet was functional. Both ponds were in ~~good~~ compliance.

16d. The coarse ~~fetu~~ refuse haul road was being watered at the time of this inspection. The operator is currently working on a chemical treatment program to enhance dust suppression.

Copy of report mailed to D. Griffin (OSM) & Barry Grosely (KCC)

Copy of report given to J. Helfrich & J. Whitehead

Inspector's signature Jim Fricke 8-3-87 No. 22

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE