REC 6-16-87

0017

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/007

Inspection Date 6/9/87

Permittee/Operator Name Kaiser Coal Corp. (KCC)

Business Address P.O. Box D

City Sunnyside State UT Zip 84539

Mine Sunnyside Complex ☐ Surface ☒ Underground ☐ Other

County Carbon State UT

Company Official(s) Barry Grosely & Byron Allred

State Official(s) Jim Fricke & Bill Malencik

Time of inspection 8:30 ☒ a.m. ☐ p.m. to 4:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 5/21/87 Weather conditions Clear

Acreage 14,535 ☒ Permitted 287.4 ☒ Disturbed ☐ Regraded ☐ Seeded 287.4 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

LB

INSPECTION REPORT COMMENTS

Permit No. ACT/007/007

Inspection Date 6/9/87

Please number comments to correspond with topics on previous page.

4b. Culverts RC2-1, RC3-3, RC3-4, RC3-5, RC3-6, MCU and Rail Cut C-1, Rail Cut Pond, Refuse Road Pond, 001 Mine Water Pond, and the SSSF pond outlets were inspected for outlet erosion protection. Protection is adequate on these culverts.

4c. The Sunnyside Surface Facilities pond was inspected as part of NOV-86-4-1 part B. The pond is constructed and in functional condition. The operator is working on the as-built drawings and should have them submitted by June 30, 1987. The Coarse Refuse Toe pond was inspected after construction. The pond is functional and the operator is working on the as-built plans.

Copy of report mailed to D. Griffin (OSM) Barry Grosely (KCC)

Copy of report given to J. Helfrich & J. Whitehead

Inspector's signature Jim Tucke 6/11/87 No. 22

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE