STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

May 16, 1988

TO: John Whitehead, Permit Supervisor

FROM: Pamela Grubaugh-Littig, Reclamation Engineer pgl

RE: Mid-Term Review and Site Visit Report, Kaiser Coal Corporation, Sunnyside Mine, ACT/007/007, Folder #2, Carbon County, Utah

The mid-term review site visit was conducted on May 11, 1988, at the Sunnyside Mine. John Whitehead, Jim Fricke and Pamela Grubaugh-Littig represented DOGM, and Barry Crosley represented Kaiser Coal Corporation.

The surface facilities map was checked versus on-the-ground activity. The recently built coarse refuse toe sediment pond needs to be correctly portrayed on the surface facilities map.

The soil borrow area for reclamation (Area 7) was noted. The TA stated that this soil borrow will be used to reclaim the coarse refuse, slurry ponds, and coal seams in the portal areas. This soil area, however, is proposed for transfer to Sunnyside Fuel Corporation. Kaiser will need to find a new soil borrow area (or document there is enough soil borrow in the permit area) when this soil is transferred to Sunnyside Fuel Corporation.

MID-TERM REVIEW

UMC 783.24 Maps: General Requirements-(PGL)

(a) Due to the sale of part of the Kaiser Sunnyside approved permit area to Sunnyside Fuel Corporation and contingent upon transfer of that area to Sunnyside Fuel Corporation, Kaiser must update the surface ownership maps to reflect the owners of record contiguous to the permit area.

UMC 784.13 Reclamation Plan: General Requirements-(PGL)

(b)(2) The detailed cost estimate should include the costs of culvert removal.

John Whitehead
ACT/007/007
9075R/53-54

(b)(3) The topsoil plan should be revised for adequacy of amounts of topsoil if the "soil borrow area" (638,650 cy) is transferred to Sunnyside Fuel Corporation.

UMC 784.23 Operation Plan: Maps and Plans-(PGL)

The surface facilities map must be updated to reflect the site as it currently exists. The symbols to indicate the facilities on the surface facilities map must be accurate.

The narrative on page 3-81, section 3.3.1, should be corrected. The sentence "Kaiser Coal Corporation originally leased the No. 2 Mine from Utah Fuel Company in 1942" seems incorrect. Kaiser Coal Corporation was not in existence then; it should read Kaiser Steel. Please revise.

djh
9075/53-54