7175

0011

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Ok RVS

inspection report

Permit No. ACT/007/007

Inspection Date OCT. 11, 1989

Permittee/Operator Name SUNNYSIDE RECLAMATION & SALVAGE, INC.

Business Address P.O. BOX 99

City SUNNYSIDE State UT Zip 84539

Mine ~~CARBON~~ SUNNYSIDE ☐ Surface ☒ Underground ☐ Other

County CARBON State UT

Company Official(s) KARL HOOKEEPER

State Official(s) BILL WARMACK

Time of inspection 9:30 ☒ a.m. ☐ p.m. to 11:30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection SEPT. 19, 1989 Weather conditions WARM

Acreage ☐ Permitted ☐ Disturbed ☐ Regraded ☐ Seeded ☐ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☐	☐	☐	☐
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☒
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☐	☐	☐	☐
c Surfacing	☐	☐	☐	☐
d Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/007

Inspection Date 10/11/89

Please number comments to correspond with topics on previous page.

4C. SEDIMENT PONDS: CONSTRUCTION OF THE NEW MINE WATER DISCHARGE POND IS NEAR COMPLETION. A BERM HAS BEEN CONSTRUCTED AROUND THE PERIMETER OF THE DISTURBED AREA & ALSO AROUND THE TOPSOIL PILE. INLET & OUTLET PIPES NEED TO BE INSTALLED BETWEEN THE TWO WHITMORE PONDS & UPON COMPLETION, THE ENTIRE SITE WILL BE REVEGETATED.

9. ENVIRONMENTAL VALUES: GRASSY TRAIL CREEK WAS OBSERVED ABOVE & BELOW THE MINE WATER CONFLUENCE & ALSO AT THE RODEO GROUNDS. THE AREAS ALONG THE STREAM BANKS HAVE BEEN HEAVILY TRAMPLED BY CATTLE DURING RECENT MIGRATIONS. THE EDGES ALONG THE STREAM CHANNEL THAT WERE ONCE DISCOLORED ARE NOW SHOWING SIGNIFICANT SIGNS OF GREEN ALGAE, INDICATING THE STREAM IS "SELF-CLEANING". SNAILS WERE OBSERVED AT THE RODEO GROUNDS LOCATION.

Copy of report mailed to

Copy of report given to

Inspector's signature William A. Warmack 10/12/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/007

Inspection Date 10/11/89

Please number comments to correspond with topics on previous page.

1d. ROAD MAINTENANCE: THE HAUL ROAD TO THE REFUSE PILE APPEARED IN GOOD CONDITION. SRS HAS UTILIZED A CHEMICAL TREATMENT TO SUPPRESS THE DUST, HOWEVER, RESULTS HAVE NOT BEEN SATISFACTORY. MR. WATT (SRS) STATED THAT THE INITIAL APPLICATION DID NOT WORK AS WELL AS THEY HOPED & THAT A NEW SUPPLY OF CHEMICAL WILL BE TRIED AGAIN. DEPENDING UPON THESE RESULTS, SRS WILL DETERMINE IF WATER APPLICATION IS STILL REQUIRED.

Copy of report mailed to JOE HELFRICH (DOGM) BRIAN SMITH (OSM) KARL HANSKEEPER (SRS)

Copy of report given to PFO

Inspector's signature William A. Warnock 10/12/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer