0050

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. — ACT/007/007

Inspection Date May 9, 1989

Permittee/Operator Name SRS (Kaiser Coal Corp)

Business Address P.O. Box 99

City Sunnyside State Ut Zip 84539

Mine Sunnyside ☐ Surface ☒ Underground ☐ Other

County Carbon State Ut

Company Official(s) Karl Housekeeper

State Official(s) Bill Malenak

Time of inspection 8:00 ☒ a.m. ☐ p.m. to 5:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection April 21, 1989 Weather conditions Clear/Warm

Acreage ☐ Permitted ☐ Disturbed ☐ Regraded ☐ Seeded ☐ Bonded

Enforcement Action NONE
Pending violations are listed herein

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☒	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☒	☒	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☒	☐	☒
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. —

Inspection Date May 9, 1989

Please number comments to correspond with topics on previous page.

General Comments: The mine areas covered in this partial inspection included Grassy Trail Creek, Scelanbu Wash, Fan Canyon, Number Two Canyon, Tipple Area, Mainshaft Area, Whitmore Pond and Twin Shafts Area.

NOV N 89-26-1-1 is still pending and has not been terminated. This NOV was associated with oil and grease problem brought about as a result of a valve failure on the longwall emulsion line located underground. Prior samples, three in number had shown the discharge from station 002 to be within limits. However, the NOV was modified on 4/6/89 and the sample on the modified abatement date was 12.2 which exceeded the 10.0 mg/l for oil & grease.

C.O's C 89-25-1-1 and C 89-25-2-1 issued 4/19/89 are still pending and have not been terminated.

Permit. Company Mine Officials in April received a letter from the DOGM Director that a conditional approval had been granted on the permit transfer to SRS.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. —

Inspection Date May 9, 1989.

Please number comments to correspond with topics on previous page.

Sediment Ponds & Impoundments. All sediment ponds were checked and no problems noted. The Whitmore pond was checked. The mine water was being treated with a flocculent, metered and pumped into the mine water line before it enters the Whitmore Pond. The color of the pond had changed from the milky to a darker color. The pond has a skimmer and a boom to absorb oil and grease. Straw bales, silt fences, and oil booms were installed in the outlet drainage.

Water Monitoring: Water monitoring associated with the violations noted herein were reviewed. The operator is taking additional water samples on a daily basis. The bulk of the samples show the operator to be in compliance with permit requirements. However at times the sample fluctuates without any reasonable explaination.

Fish, Wildlife & Environmental Values. At the suggestion of Harry Dalton, Utah Division of Wildlife, the operator had previously placed five permeable (water) barriers in Grassy Trail to prevent Whitmore Pond material from moving downstream. They appear to be working effectively

Copy of report mailed to SLC FOR: OSM ; DOGM/Joe Helfrich

Copy of report given to Operator/Karl Housekeeper

" " " filed PFO

Inspector's signature Wm. J. Malencik No. 26

5/15/89

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049