0026

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/007
Inspection Date March 15, 1990

Permittee/Operator Name SRS
Business Address P.O. Box 99
City Sunnyside State Ut Zip 84539
Mine Sunnyside ☐ Surface ☒ Underground ☐ Other
County Carbon State
Company Official(s) Karl Housekeeper
State Official(s) Bill Malencik
Time of inspection 1:00 ☐ a.m. ☒ p.m. to 3:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 2/27/1990 Weather conditions Pt. Cloudy/Cool
Acreage 14475 ☐ Permitted 310 ☐ Disturbed ☐ Regraded ☐ Seeded 287 ☐ Bonded
Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☒
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☒	☐	☐	☒
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/007

Inspection Date 3/15/90

Please number comments to correspond with topics on previous page.

Permit. The operator submitted a proposal for an incidental boundary change. This is associated with a Geneva Steel coal lease (state) that SRS has plans to mine. The lease is now under the control of SRS.

Stream Channel Diversion: Grassy Trail Creek was frozen in the upper reaches i.e., Rodeo Grounds upstream. The upper area had about three inches of snow cover.

Sediment Ponds & Impoundments:

- Neither Whitmore #1 nor Whitmore #2 were discharging. Furthermore, mine water was not coming into either pond.
- SSF pond was discharging
- Pasture pond was dry.
- Coarse Refuse pond was dry and the pond inslope rills graded last fall held up over the winter.
- Railcut pond, dry and the pond slopes were seeded last fall. No seedlings were observed.
- Clear Water pond had recently been cleaned.
- Slurry cell #2 had been cleaned. #1 was being cleaned.

Other Support Facilities: A water well that had been cased had just been completed on the Mainshaft Pad.

Copy of report mailed to {SRS/ Karl Housekeeper; SEC For OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature [signature] No. 26

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

3/21/90