0011

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/007

Inspection Date 6/4/91

Permittee/Operator Name Sunnyside Coal Co.

Business Address P.O. Box 99

City Sunnyside State Ut Zip 84539

Mine Sunnyside ☐ Surface ☒ Underground ☐ Other

County Carbon State Ut.

Company Official(s) Karl Housekeeper

State Official(s) Bill Malencak

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 3:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection May Weather conditions Clear/Windy/Temp 60's

Acreage 14.475 ☐ Permitted 310 ☐ Disturbed ☐ Regraded ☐ Seeded 287 ☐ Bonded

Enforcement Action None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/007

Inspection Date 6/4/91

Please number comments to correspond with topics on previous page.

General Comments. Two pending items from the April and May inspections required following action. The permittee has completed work as required and as follows:

- Manshaft Sediment Pond (April Report) Concrete cap has been has been placed on the principal spillway. The cap was placed where the pipe came out of the ground.
- Coal Loadout Culvert. The culvert and ditch near the coal loadout was cleaned. The problem appears to be coal fines that blow into the ditch.

Sediment Ponds & Impoundments. The permittee and the undersigned checked in the field 18 impoundments, of which 10 are sediment ponds. All ponds were stable. The Turnshafts impoundment contained mine water, but was not discharging. The new Whitmore pond (mine water) was discharging into Pole Creek.

Others. Grassy Trail Creek was dry at the upper end of the mine site, but was also dry at Sunnyside Park. In between these two points, mine water was flowing. The water is being used to irrigate hay fields above the park

Copy of report mailed to SCC/Karl Housekeeper; OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ file RFO

Inspector's signature Tim J. Malenick No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

6/11/91

DOGM/IR-2

an equal opportunity employer

11/86 001049