0005

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Ted Stewart
Executive Director

James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

INSPECTION REPORT

Partial: X Complete: ___ Exploration: ___
Inspection Date & Time: August 10, 1994, 2:00 pm to 3:30 pm
Date of Last Inspection: July 21, 1994

Mine Name: Sunnyside Coal Mine County: Carbon Permit Number: **ACT/007/007**
Permittee and/or Operator's Name: Sunnyside Coal Company (SCC)
Business Address: PO Box 99, Sunnyside, Utah 84539
Type of Mining Activity: Underground X Surface ___ Prep. Plant ___ Other ___
State Officials(s): Henry Sauer
Company Official(s): Darrel Leonard
Federal Official(s): ___
Weather Conditions: Clear and warm
Existing Acreage: Permitted-14475 Disturbed-310 Regraded-0 Seeded-0 Bonded-310
Increased/Decreased: Permitted-___ Disturbed-___ Regraded-___ Seeded-___ Bonded-___
Status: __Exploration/ X Active/__Inactive/__Temporary Cessation/__Bond Forfeiture
Reclamation (__Phase I/__Phase II/__Final Bond Release/__Liability_____Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions
1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[ ]	[ ]	[ ]	[ ]
2. SIGNS AND MARKERS	[ ]	[ ]	[ ]	[ ]
3. TOPSOIL	[ ]	[ ]	[ ]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[ ]	[ ]	[ ]	[ ]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[X]	[ ]	[X]	[ ]
c. OTHER SEDIMENT CONTROL MEASURES	[X]	[ ]	[X]	[ ]
d. WATER MONITORING	[ ]	[ ]	[ ]	[ ]
e. EFFLUENT LIMITATIONS	[ ]	[ ]	[ ]	[ ]
5. EXPLOSIVES	[ ]	[ ]	[ ]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	[ ]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
8. NONCOAL WASTE	[ ]	[ ]	[ ]	[ ]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[ ]	[ ]	[ ]	[ ]
10. SLIDES AND OTHER DAMAGE	[ ]	[ ]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[ ]	[ ]	[ ]	[ ]
12. BACKFILLING AND GRADING	[ ]	[ ]	[ ]	[ ]
13. REVEGETATION	[ ]	[ ]	[ ]	[ ]
14. SUBSIDENCE CONTROL	[ ]	[ ]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[ ]	[ ]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[ ]	[ ]	[ ]	[ ]
b. DRAINAGE CONTROLS	[ ]	[ ]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[ ]	[ ]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	[ ]	[X]	[ ]
19. AVS CHECK (4th Quarter-April, May, June)_____(date)	[ ]	[ ]	[ ]	[ ]
20. AIR QUALITY PERMIT	[ ]	[ ]	[ ]	[ ]
21. BONDING & INSURANCE	[ ]	[ ]	[ ]	[ ]

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/007/007 DATE OF INSPECTION: 8/10/94

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE:

b. SEDIMENT PONDS AND IMPOUNDMENTS

The Hoist House Pond was being enlarged at the time of the inspection. This is required because the pond does not have the capacity to contain the design event. The Upper No. Two Canyon pond has been enlarged for the same reason stated above. Both ponds will require recertification by a professional engineer.

c. OTHER SEDIMENT CONTROL MEASURES

The silt fence immediately above the water tipple needs minor maintenance. Since it was obvious that it had rained recently, I suggested that Mr. Leonard inspect all the silt fences on the property and perform maintenance on them if necessary.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

The roof on the No. Two Canyon storage shed has been removed. The majority of the material stored in the shed has been removed.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), Darrel Leonard (SCC)
Given to: Joe Helfrich (DOGM)

Inspector's Signature: Henry Sauer #32 Date: August 24, 1994

SUNNY.894