0002

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/007

Inspection Date 5/10/95

Permittee/Operator Name SUNNYSIDE COAL MINE

Business Address P.O. BOX 99, SUNNYSIDE, UT.

City SUNNYSIDE State UT. Zip 84539

Mine SUNNYSIDE COAL MINE ☐ Surface ☑ Underground ☐ Other

County CARBON State UT.

Company Official(s) BOB BURNHAM

State Official(s) HENRY SAUER

Time of inspection 1:00 ☐ a.m. ☑ p.m. to 4:00 ☐ a.m. ☑ p.m. ☑ Partial ☐ Complete

Date of last inspection 4/13/95 Weather conditions COOL AND OVERCAST

Acreage ☐ Permitted ☐ Disturbed ☐ Regraded ☐ Seeded ☐ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☑	☐	☐	☑
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☑	☐	☐	☑

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/007

Inspection Date 5/10/95

Please number comments to correspond with topics on previous page.

8) All of the PCB-Transformers and PCB-fluids are now located inside the Truck Shop. The transformers and fluids including oil, grease and solvents formally stored in the No 2 Canyon Material Storage Area and between the Bath House and the Main Office are contained within a plastic lined, curbed area.

Mr. Burham was instructed to remove the noncoal waste from the facilities area and place it in the No 2 Canyon Noncoal Waste Pile. Noncoal waste has "built up" again in response to the demolition activity on site.

13) The portals south of the Truck Shop immediately north of the Wash Plant Dugway have been backfilled. The No 4 Mine Portal and the Main Belt Portal have also been backfilled. During the inspection the Man Trip Portal was being backfilled. Most of the backfill material has been borrowed from the pile of soil/spoil excavated from the Hoist House Sediment Pond.

Copy of report mailed to Bob Burnham (SCC), Steve Railburn (OSM)

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature Henry Sauer No. 32

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE