0021

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

RECEIVED
APR 2 2 1991
DIVISION OF
OIL GAS & MINING

INSPECTION REPORT

PERMIT NO.: ACT/007/011 Inspection Date: April 16, 1991
Permittee and/or Operators Name: U.S. Fuel Company
Business Address: P.O. Box A
City: Hiawatha State: Utah Zip: 84527
Mine Name: Hiawatha Complex County: Carbon State: Utah
Type of Mining Activity: Underground XX Surface ____ Other ____
Company Official (s): Mike Watson
State Officials (s): Stephen J. Demczak DOGM
Time of Inspection: 9:00 (X)a.m. ( ) p.m. to 12:15 ( )a.m. (X)p.m.
Partial XX Complete: ____ Date of Last Inspection: 3/25/91
Weather Conditions: Warm
Acreage: Permitted 20,700 Disturbed 290 Regraded ____ Seeded ____
Bonded 290 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

		YES	NO	N/A	COMMENTS
1.	PERMITS	( )	( )	( )	( )
2.	SIGNS AND MARKERS	( )	( )	( )	( )
3.	TOPSOIL	(X)	( )	( )	(X)
4.	HYDROLOGIC BALANCE:				
	a. STREAM CHANNEL DIVERSIONS	(X)	( )	( )	(X)
	b. DIVERSIONS	( )	( )	( )	( )
	c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	( )	( )	( )
	d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
	e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
	f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5.	EXPLOSIVES	( )	( )	( )	( )
6.	DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7.	COAL PROCESSING WASTE	( )	( )	( )	( )
8.	NONCOAL WASTE	( )	( )	( )	( )
9.	PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10.	SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11.	CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12.	BACKFILLING AND GRADING	( )	( )	( )	( )
13.	REVEGETATION	( )	( )	( )	( )
14.	SUBSIDENCE CONTROL	( )	( )	( )	( )
15.	CESSATION OF OPERATIONS	( )	( )	( )	( )
16.	ROADS				
	a. CONSTRUCTION	( )	( )	( )	( )
	b. DRAINAGE CONTROLS	( )	( )	( )	( )
	c. SURFACING	( )	( )	( )	( )
	d. MAINTENANCE	( )	( )	( )	( )
17.	OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18.	SUPPORT FACILITIES UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT COMMENTS
(continuation sheet)

PERMIT NO. ACT/007/011 INSPECTION DATE April 16, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

3. TOPSOIL:

The topsoil piles were in good condition showing no signs of wind or water erosion. The topsoil piles were undisturbed and they have adequate ditches around them.

4. HYDROLOGIC BALANCE:

a. Stream Channel Diversions:

The diversions above the Southfork loadout facilities were still uncleaned. The NOV 91-39-1-4 abatement is due on April 25, 1991 on this issue.

Comments: The operator was told to notify DOGM of mine closures in writing. It was told to the representative that loading of coal is considered mining. The Hiawatha Complex will still be shipping coal from stock piles during mine shut-down. It appears the Hiawatha Complex will not open again, but the company is actively trying to sell the mine property or its leases. Inspections will be made monthly.

Copy of report:

Mailed to: Bob Eccli (USFC)
Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)
Filed to: PFO

Inspectors Signature and Number: Stephen J.Demczak #39 Date: 4/18/91

Stephen J Demczak #39