007/011 #2

0031

UNITED STATES FUEL COMPANY

340 Hardscrabble Rd.
Helper, Utah 84526

(801) 472-3372
FAX (801) 472-3384

February 27, 1997

Utah Coal Regulatory Program
Division of Oil, Gas and Mining
Department of Natural Resources
1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, UT 84114-5801
Attn. Daron Haddock

RECEIVED
MAR 03 1997
DIV. OF OIL, GAS & MINING

Re: Highwall Survey

I have enclosed the United States Fuel Co. response to the Highwall survey. Please call if you require further information.

Sincerely,

Michael P. Watson

Michael P. Watson
President

UDOGM HIGHWALL SURVEY
February 1997

MINE NAME Hiawatha Complex

PERMIT NUMBER ACT/007/011

1. Identify each highwall used in connection with the mine and provide a description of its location and extent. (reference maps where highwall is shown)

King 4 intake portals	Middle Fork Upper Bench	V-11
King 4 belt and return portal	Middle Fork Upper Bench	V-11
King 5 portals	Middle Fork Upper Bench	V-11
King 6 / King 3 intake and return portals	South Fork Lower Bench	V-12
Hiawatha 1 & 2, King 1 & 2, South Fork "B" and "A" Seams		Pre-Act

2. Provide verification of highwall and adjacent cutslope creation dates. (At a minimum determine whether it was created before or after May 3, 1978.)

King 4 intake portals	1975
King 4 belt and return portals	1975
King 5 portals	initial highwall pre-1978, portals installed in the spring of 1978
King 6 / King 3 portals	approx. 1947

3. Provide a reference to the Mining and Reclamation Plan (MRP) which discusses the final reclamation and elimination or retention of the identified highwalls. If no reference exists, state "none".

Pages 72 and 76 of Chapter II Soils

Please return to Daron Haddock by March 7, 1997