0009

File

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

Permittee and/or Operators Name: US Steel
Business Address: PO Box 1270 Price Co 84528
Mine Name: Wellington Preparation Plant Permit Number: ACT/007/012
Type of Mining Activity: Underground ___ Surface ___ Other ✓
County: Carbon
Company Official(s): Filas
State Official(s): Tom Wright Holland Shepherd
Inspection Date and Time: 10/30
Partial: ✓ Complete: ___ Date of Last Inspection: 9/20
Weather Conditions: Sunny
Acreage: Permitted ___ Disturbed ___ Regraded ___ Seeded ___ Bonded ___
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	Comments
1. PERMITS				
2. SIGNS AND MARKERS				
3. TOPSOIL				
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS				
b. DIVERSION'S				
c. SEDIMENT PONDS AND IMPOUNDMENTS				
d. OTHER SEDIMENT CONTROL MEASURES				
e. SURFACE AND GROUNDWATER MONITORING				
f. EFFLUENT LIMITATIONS				
5. EXPLOSIVES				
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL				
7. COAL PROCESSING WASTE				
8. NONCOAL WASTE				
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES				
10. SLIDES AND OTHER DAMAGE				
11. CONTEMPORANEOUS RECLAMATION				
12. BACKFILLING AND GRADING				
13. REVEGETATION				
14. SUBSIDENCE CONTROL	✓			✓
15. CESSATION OF OPERATIONS				
16. ROADS				
a. CONSTRUCTION				
b. DRAINAGE CONTROLS				
d. SURFACING				
e. MAINTENANCE				
17. OTHER TRANSPORTATION FACILITIES				
18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS				

INSPECTION REPORT
(Page 2)

Permit Number: Act /007/012 Date of Inspection: 10/30/85

COMMENTS

(Comments are Numbered to Correspond with Topics Listed Above)

#13 Test plot completed at coarse refuse area straw crimped in fence not completed yet Some fertilizer and seed present

Test plots completed at slurry ponds. Plots (2) are adjacent fence installed around perimeter

Files stated that topsoil areas east of slurry ponds have been modified. Unable to check during this inspection due to meeting on different site. Should be checked on next inspection

Copy of this Report:
Mailed to: Randy Watts, Barbara Filas
Given to:

Inspectors Signature and Number: Thomas W Wright #8

0365Q 1-2