0010

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/012

Inspection Date July 13, 1990

Permittee/Operator Name Genwal Coal Co. / Castle Valley Resources, Inc.

Business Address P.O. Box 766

City Wellington State Utah Zip 84524

Mine Wellington Prep Plant ☐ Surface ☐ Underground ☒ Other

County Carbon State Utah

Company Official(s) Candy Manzanares

State Official(s) Daron Haddock, Johnny Pappas

Time of Inspection 12:30 ☐ a.m. ☒ p.m. to 2:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection June 29, 1990 Weather conditions Mostly Sunny, Hot

Acreage 1720 ☐ Permitted 356 ☐ Disturbed 1.5 ☐ Regraded 1.5 ☐ Seeded 469 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☒
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT 007/012

Inspection Date July 13, 1990

Please number comments to correspond with topics on previous page.

2. Signs & Markers: Mine ID signs were checked and found at all points of access to the property. Disturbed area perimeter markers (white roof bolts) are in place. Topsoil markers are up.

4b Diversions: No major problems were noted in any of the diversions. Some minor maintenance is scheduled to correct rilling in the undisturbed bypass diversion at the south end of the property.

4c. Sediment ponds: The main sediment pond was checked. The pond was dry and appears to have adequate storage capacity.

9. Protection of fish wildlife: Both Antelope and Mule deer were seen on the property.

13. Revegetation: Vegetation is very sparse in areas recently seeded. The site has been extremely dry, which would account for the low germination of seed. Straw mulch is still very much apparent in the soil and with the proper moisture vegetation may yet be established.

Copy of report mailed to Candy Manzanarez

Copy of report given to Joe Helfrich (DOGM) John Kathman (OSM)

Inspector's signature Daron R. Haddock No. 28

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE