0005

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor

Ted Stewart
Executive Director

James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: X Complete:___ Exploration:___
Inspection Date & Time: 11/28/94/9:00am-1100am
Date of Last Inspection: 10/28/94

Mine Name: Wellington Prep Plant County: Carbon Permit Number: **ACT/007/012**
Permittee and/or Operator's Name: Nevada Electric Investment Company (NEICO)
Business Address: c/o Genwal Coal Company, P.O. Box 1201, Huntington, Utah 84528
Type of Mining Activity: Underground___ Surface___ Prep. Plant XXX Other___
Company Official(s): Randy Gainer
State Officials(s): Stephen J. Demczak Federal Official(s):_____
Weather Conditions: Cool/Teen's
Existing Acreage: Permitted- 1720 Disturbed- 356 Regraded- 1.5 Seeded- 1.5 Bonded- 744
Increased/Decreased: Permitted-___ Disturbed-___ Regraded-___ Seeded-___ Bonded-___
Status: __Exploration/ XXX Active/__Inactive/__Temporary Cessation/__Bond Forfeiture
Reclamation (__Phase I/__Phase II/__Final Bond Release/__Liability_____ Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]	[ ]	[X]	[ ]
2. SIGNS AND MARKERS	[X]	[ ]	[X]	[ ]
3. TOPSOIL	[ ]	[ ]	[ ]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[X]	[ ]	[X]	[ ]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[X]	[ ]	[X]	[ ]
c. OTHER SEDIMENT CONTROL MEASURES	[ ]	[ ]	[ ]	[ ]
d. WATER MONITORING	[ ]	[ ]	[ ]	[ ]
e. EFFLUENT LIMITATIONS	[ ]	[ ]	[ ]	[ ]
5. EXPLOSIVES	[ ]	[ ]	[ ]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	[ ]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]	[ ]	[X]	[ ]
8. NONCOAL WASTE	[ ]	[ ]	[ ]	[ ]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[ ]	[ ]	[ ]	[ ]
10. SLIDES AND OTHER DAMAGE	[ ]	[ ]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[ ]	[ ]	[ ]	[ ]
12. BACKFILLING AND GRADING	[ ]	[ ]	[ ]	[ ]
13. REVEGETATION	[ ]	[ ]	[ ]	[ ]
14. SUBSIDENCE CONTROL	[ ]	[ ]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[ ]	[ ]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[ ]	[ ]	[ ]	[ ]
b. DRAINAGE CONTROLS	[ ]	[ ]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[ ]	[ ]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[ ]	[ ]	[ ]	[ ]
19. AVS CHECK (4th Quarter-April, May, June)_____(date)	[ ]	[ ]	[ ]	[ ]
20. AIR QUALITY PERMIT	[ ]	[ ]	[ ]	[ ]
21. BONDING & INSURANCE	[ ]	[ ]	[ ]	[ ]

INSPECTION REPORT
(Continuation sheet)

PERMIT NUMBER: ACT/007/012 DATE OF INSPECTION: 11/28/94

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT -

The Dryer Pond "as-built" was reviewed in the field. The drawing was complete and accurate with final construction. The pond drawing is under review and approval at the division.

2. SIGNS AND MARKERS -

The operator has installed additional perimeter markers at the railroad tracks, since the last inspection. Several markers were missing due to vandalism.

4a. DIVERSION -

Several diversions have been cleaned out since the last inspection. The ditches were spot checked and were clear of obstructions.

4b. SEDIMENT POND AND IMPOUNDMENTS -

The sediment ponds were not discharging water during the inspection. All ponds were dry, except the rail loadout pond. There were no signs of erosion to inlets or outlets of the ponds. The structure appeared to be stable with no hazardous conditions existing.

7. REFUSE PILES -

The Course Refuse Pile may come under a division order for up-dating the Mining and Reclamation Plan concerning contemporaneous reclamation of the first lift. The division order is under review in Salt Lake City DOGM.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas , and Mining.

Copy of this Report:

Mailed to: Randy Gainer (NEICO) Bernie Freeman (OSM)
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office
Date: December 5, 1994

Inspector's Signature: Stephen J. Demczak #39
Stephen J. Demczak