0008

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/013

Inspection Date July 18, 1989

Permittee/Operator Name KAISER COAL CORPORATION

Business Address P.O. BOX 1107

City RATON State NM Zip 87740

Mine HORSE CANYON ☐ Surface ☒ Underground ☐ Other

County CARBON State UT

Company Official(s) NONE

State Official(s) BILL WAKMACK & BILL MAKEWICK

Time of inspection 11:00 ☒ a.m. ☐ p.m. to 2:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection JUNE 28 & 29, 1989 Weather conditions HOT

Acreage 1917 ☒ Permitted 30 ☒ Disturbed ☐ Regraded ☐ Seeded 30 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☐	☐	☐	☐
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/013

Inspection Date July 18, 1989

Please number comments to correspond with topics on previous page.

GENERAL: BILL MALEWICZ (DOGM) ACCOMPANIED THE UNDERSIGNED ON THIS INSPECTION. GROUND CONDITIONS WERE VERY DRY, NO PHYSICAL EVIDENCE PRESENT INDICATING PREVIOUS PRECIPITATION HAD OCCURRED. SEDIMENT PONDS & HORSE CANYON CREEK WERE DRY.

2. SIGNS & MARKERS: SIGNS WERE LEGIBLE & DISTURBED AREA MARKERS HAVE BEEN INSTALLED TO CLEARLY IDENTIFY THESE AREAS.

4d. OTHER SEDIMENT CONTROLS: SILT FENCES WERE IN GOOD REPAIR. ADDITIONAL SILT FENCES HAVE BEEN INSTALLED AS NOTED IN THE PREVIOUS INSPECTION.

18. SUPPORT FACILITIES: AS OF THIS INSPECTION, IT COULD NOT BE DETERMINED WHETHER OR NOT THE WORK HAS BEEN COMPLETED AT THE TWO LILA CANYON BREAKOUTS (SEE 6/28 & 29 INSPECTION REPORTS), ALTHOUGH BIDS WERE TO BE RECEIVED FOR THE WORK.

Copy of report mailed to JOE HEFFICH (DOGM), BRIAN SMITH (OSM) JOHN PALEY (KCC)

Copy of report given to PFO

Inspector's signature William A. Warnock 7/21/89 No. 30

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE