2070

0014

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

RUS

inspection report

Permit No. ACT/007/013

Inspection Date OCT. 11, 1989

Permittee/Operator Name KAISER COAL CORPORATION

Business Address P.O. BOX 1107

City RATON State NEW MEXICO Zip 87740

Mine HORSE CANYON ☐ Surface ☒ Underground ☐ Other

County CARBON State UT

Company Official(s) NONE

State Official(s) BILL WADMACK

Time of inspection 12:00 ☐ a.m. ☒ p.m. to 2:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection SEPT. 19, 1989 Weather conditions WARM

Acreage ☐ Permitted 50 ☒ Disturbed ☐ Regraded ☐ Seeded 50 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a. Stream channel diversions	☐	☐	☐	☐
b. Diversions	☒	☐	☐	☐
c. Sediment ponds and impoundments	☒	☐	☐	☒
d. Other sediment control measures	☒	☐	☐	☒
e. Surface and groundwater monitoring	☐	☐	☐	☐
f. Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a. Construction	☐	☐	☐	☐
b. Drainage controls	☐	☐	☐	☐
c. Surfacing	☐	☐	☐	☐
d. Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/013

Inspection Date 10/11/89

Please number comments to correspond with topics on previous page.

GENERAL: SITE WAS VERY DRY, ALTHOUGH THE RIGHT FORK OF HORSE CANYON WAS FLOWING, estimated at less than 1 gpm. CATTLE HAVE BEEN REMOVED FROM THE AREA & HAVE TRAMPLED THROUGHOUT THE SITE. WITH THE ONSLAUGHT OF HUNTING SEASON, VEHICLE TRACKS WERE NOTICED AT MOST ACCESS ROADS INDICATING HEAVY PUBLIC USE.

4c. SEDIMENT PONDS: ALL PONDS WERE DRY, HOWEVER, CATTLE TRACKS WERE ESPECIALLY NOTICEABLE IN THESE AREAS & MAY HAVE CONGREGATED FOR WATER. NO DAMAGE TO THE EMBANKMENTS OR PIPES WAS OBSERVED.

4d. OTHER SED CONTROLS: ALL SILT FENCES WERE FUNCTIONAL & IN GOOD REPAIR CONSIDERING THE RECENT CATTLE ACTIVITY. THE TWO SILT FENCES AT THE REFUSE/LANDFILL SITE SHOULD BE CLEANED TO MAINTAIN CAPACITIES.

Copy of report mailed to

Copy of report given to

Inspector's signature William A. Warnock 10/12/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/013

Inspection Date 10/11/89

Please number comments to correspond with topics on previous page.

1d. ROAD MAINTENANCE: THE MAIN ACCESS ROAD THRU THE MINE SITE HAS BEEN RECENTLY GRADED, POSSIBLY FOR HUNTER TRAVEL. WITH THE EXTENSIVE PUBLIC USE, THE ROAD SURFACE HAS BECOME PULVERIZED & DUSTY, & MIGHT INCREASE SEDIMENT DEPOSITION ON THE SITE IF PRECIPITATION SHOULD OCCUR. THEREFORE, SITE MAINTENANCE MIGHT BE REQUIRED FOLLOWING MEASURABLE PRECIP.

18. SUPPORT FACILITIES: AT THE OFFICE/BATHHOUSE LOCATION, DOORS TO A SHOP BUILDING (RAIL SHOP) WERE OPEN. EVIDENTLY, THE LOCK ON THE ENTRANCE DOOR WAS PRIED OFF & THE LARGE WOODEN DOORS WERE THEN OPENED. NO ADDITIONAL VANDALISM WAS NOTED DURING THIS INSPECTION.

Copy of report mailed to JOE HELFRICH (DOGM), BRIAN SMITH (OSM), JOHN PALFY (KCC)

Copy of report given to PFO

Inspector's signature William A. Warnick 10/12/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE