0004

Document Information Form

Mine Number: C/007/013

File Name: Incoming

To: DOGM

From:

Person N/A

Company N/A

Date Sent: May 7, 1990

Explanation:

Discharge Monitoring Report

cc:

File in:
C/ 007 , 013 , Incoming
Refer to:
- ☐ Confidential
- ☐ Shelf
- ☐ Expandable

Date ___ For additional information

FILE #5
INA 007/013

Form Approved.
O.M.B. No. 2040-0004
Approval expires 9-30-85

PERMITTEE NAME/ADDRESS (*Include Facility Name/Location if different*)

NAME Kaiser Coal Corporation

ADDRESS P.O. Box 407

Raton, New Mexico 87740

FACILITY Horse Canyon Mine INA/007/013

LOCATION Horse Canyon

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (*NPDES*)
DISCHARGE MONITORING REPORT (*DMR*)

(2-16) PERMIT NUMBER: UT-0022926

(17-19) DISCHARGE NUMBER: See #1

*1 001a, 002a, 003a, 004a, 005a, 006a, 007a, 008a, 009a, 010a & 011a.

MONITORING PERIOD

	YEAR	MO	DAY		YEAR	MO	DAY
FROM	90	3	1	TO	90	3	31
	(20-21)	(22-23)	(24-25)		(26-27)	(28-29)	(30-31)

NOTE: Read instructions before completing this form.

PARAMETER (32-37)		(3 Card Only) QUANTITY OR LOADING (46-53) AVERAGE	(54-61) MAXIMUM	UNITS	(4 Card Only) QUALITY OR CONCENTRATION (38-45) MINIMUM	(46-53) AVERAGE	(54-61) MAXIMUM	UNITS	NO. EX (62-63)	FREQUENCY OF ANALYSIS (64-68)	SAMPLE TYPE (69-70)
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										

RECEIVED
MAY 07 1990
DIVISION OF OIL, GAS & MINING

File in:
- ☐ Confidential
- ☐ Shelf
- ☐ Expandable

Refer to Record No 0004 Date ____
In C/ 007, 013, Incoming
For additional information

NAME/TITLE PRINCIPAL EXECUTIVE OFFICER		TELEPHONE		DATE		
John Palfy Agent For Kaiser TYPED OR PRINTED	I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 USC § 1001 AND 33 USC § 1319. *(Penalties under these statutes may include fines up to $10,000 and/or maximum imprisonment of between 6 months and 5 years.)*	Paul A. Houskeeper SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR AUTHORIZED AGENT	AREA CODE: 505	NUMBER: 445-2395	YEAR: 1990	MO: 4	DAY: 10

COMMENT AND EXPLANATION OF ANY VIOLATIONS (*Reference all attachments here*)

Mine is idle. No discharge occured from any of the UPDES discharge points listed above

FILE #5
INA 007/013

Form Approved.
O.M.B. No. 2040-0004
Approval expires 9-30-85

PERMITTEE NAME/ADDRESS (*Include Facility Name/Location if different*)

NAME: Kaiser Coal Corporation

ADDRESS: P.O. Box 407
Raton, New Mexico 87740

FACILITY: Horse Canyon Mine INA/007/013

LOCATION: Horse Canyon

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)
DISCHARGE MONITORING REPORT (DMR)

(2-16) PERMIT NUMBER: UT-0022926

(17-19) DISCHARGE NUMBER: See #1

** 001a, 002a, 003a, 004a, 005a, 006a, 007a, 008a, 009a, 010a & 011a.

MONITORING PERIOD

	YEAR	MO	DAY		YEAR	MO	DAY
FROM	90	3	1	TO	90	3	31
	(20-21)	(22-23)	(24-25)		(26-27)	(28-29)	(30-31)

NOTE: Read instructions before completing this form.

PARAMETER (32-37)		(3 Card Only) QUANTITY OR LOADING (46-53) AVERAGE	(54-61) MAXIMUM	UNITS	(4 Card Only) QUALITY OR CONCENTRATION (38-45) MINIMUM	(46-53) AVERAGE	(54-61) MAXIMUM	UNITS	NO. EX (62-63)	FREQUENCY OF ANALYSIS (64-68)	SAMPLE TYPE (69-70)
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										

RECEIVED
MAY 07 1990
DIVISION OF OIL, GAS & MINING

NAME/TITLE PRINCIPAL EXECUTIVE OFFICER		TELEPHONE		DATE		
John Palfy Agent For Kaiser TYPED OR PRINTED	I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. § 1001 AND 33 U.S.C. § 1319 (*Penalties under these statutes may include fines up to $10,000 and/or maximum imprisonment of between 6 months and 5 years.*)	Paul S. Weisbecker SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR AUTHORIZED AGENT	505 AREA CODE	445-2325 NUMBER	1990 YEAR	4 MO	10 DAY

COMMENT AND EXPLANATION OF ANY VIOLATIONS (*Reference all attachments here*)

Mine is idle. No discharge occured from any of the UPDES discharge points listed above

EPA Form 3320-1 (Rev. 10-79) PREVIOUS EDITION TO BE USED UNTIL SUPPLY IS EXHAUSTED (REPLACES EPA FORM T-40 WHICH MAY NOT BE USED.)

5-2-90

Report was submitted previously. However the monitoring period was not indicated. Please enter the dates or replace the sheet.

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if different)

NAME Kaiser Coal Corporation

ADDRESS P.O. Box 407

Huntington, New Mexico 87540

FACILITY Horse Canyon Mine ACT/007/013 FILE #5

LOCATION Horse Canyon

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)
DISCHARGE MONITORING REPORT (DMR)

Form Approved.
OMB No. 2040-0004
Approval expires 9-30-85

(2-16) PERMIT NUMBER: UT-0022926

(17-19) DISCHARGE NUMBER: see #4

001a, 002a, 003a, 004a, 005a, 006a, 007a, 008a, 009a, 010a, & 011a.

MONITORING PERIOD

	YEAR (20-21)	MO (22-23)	DAY (24-25)		YEAR (26-27)	MO (28-29)	DAY (30-31)
FROM				TO			

NOTE: Read instructions before completing this form.

PARAMETER (32-37)		(3 Card Only) QUANTITY OR LOADING (46-53) AVERAGE	(54-61) MAXIMUM	UNITS	(4 Card Only) QUALITY OR CONCENTRATION (38-45) MINIMUM	(46-53) AVERAGE	(54-61) MAXIMUM	UNITS	NO. EX (62-63)	FREQUENCY OF ANALYSIS (64-68)	SAMPLE TYPE (69-70)
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										

RECEIVED
APR 12 1990
DIVISION OF OIL, GAS & MINING

NAME/TITLE PRINCIPAL EXECUTIVE OFFICER		TELEPHONE		DATE		
John Palfy Agent for Kaiser	I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN, AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 USC § 1001 AND 33 USC § 1319 (Penalties under these statutes may include fines up to $10,000 and/or maximum imprisonment of between 6 months and 5 years.)	Scott Ellsworth	505	445-2395	1990	4	10
TYPED OR PRINTED		SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR AUTHORIZED AGENT	AREA CODE	NUMBER	YEAR	MO	DAY

COMMENT AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

Mine idle. No discharge occured from any of the UPDES discharge points listed above.

EPA Form 3320-1 (Rev. 10-79) PREVIOUS EDITION TO BE USED UNTIL SUPPLY IS EXHAUSTED (REPLACES EPA FORM T-40 WHICH MAY NOT BE USED.)

GENERAL INSTRUCTIONS

1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
2. Enter "PERMITTEE NAME/MAILING ADDRESS (and facility name/location, if different)," "PERMIT NUMBER," and "DISCHARGE NUMBER" where indicated. (A separate form is required for each discharge.)
3. Enter dates beginning and ending "MONITORING PERIOD" covered by form where indicated.
4. Enter each "PARAMETER" as specified in monitoring requirements of permit.
5. Enter "SAMPLE MEASUREMENT" data for each parameter under "QUANTITY" and "QUALITY" in units specified in permit. "AVERAGE" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "MONITORING PERIOD." "MAXIMUM" and "MINIMUM" are normally extreme high and low measurements obtained during "MONITORING PERIOD." (NOTE to municipals with secondary treatment requirement, enter 30-day average of sample measurements under "AVERAGE" and enter maximum 7-day average of sample measurements obtained during monitoring period under "MAXIMUM".
6. Enter "PERMIT REQUIREMENT" for each parameter under "QUANTITY" and "QUALITY" as specified in permit.
7. Under "NO. EX" enter number of sample measurements during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
8. Enter "FREQUENCY OF ANALYSIS" both as "SAMPLE MEASUREMENT" (actual frequency of sampling and analysis used during monitoring period) and as "PERMIT REQUIREMENT" specified in permit. (e.g., Enter "CONT." for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
9. Enter "SAMPLE TYPE" both as "SAMPLE MEASUREMENT" (actual sample type used during monitoring period) and as "PERMIT REQUIREMENT." (e.g., Enter "GRAB" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)

(FOLD HERE FIRST)

10. WHERE VIOLATIONS OF PERMIT REQUIREMENTS ARE REPORTED, ATTACH A BRIEF EXPLANATION TO DESCRIBE CAUSE AND CORRECTIVE ACTIONS TAKEN. REFERENCE EACH VIOLATION BY DATE.
11. If "no discharge" occurs during monitoring period, enter "NO DISCHARGE" across form in place of data entry.
12. Enter "NAME/TITLE OF PRINCIPAL EXECUTIVE OFFICER" with "SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR AUTHORIZED AGENT," "TELEPHONE NUMBER" and "DATE" at bottom of form.
13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
14. More detailed instructions for use of this DISCHARGE MONITORING REPORT (DMR) form may be obtained from Office(s) specified in permit.

LEGAL NOTICE

quired by law (33 U.S.C. 1318; 40 C.F.R. 125.27). Failure to report or failure to report truthfully can ,000 per day of violation; or in criminal penalties not to exceed $25,000 per day of violation, or by imp than ear, or by both.

(FOLD HERE SECOND)

Salt Lake City, Utah 84180-1203
355 West North Temple, 3 Triad Center, Suite 350
Attention: Water Quality Division
EPA
Environmental Protection Agency
P.O. Box
San Francisco, California 94501

SUNNYSIDE, UT
MAY 2
1990
PM

(FOLD HERE THIRD)

STAPLE HERE

PERMITTEE NAME/ADDRESS (*Include Facility Name/Location if different*)

NAME Kaiser Coal Corporation

ADDRESS P.O. Box 407

Gunnison, Utah 84634

FACILITY Emery Canyon Mine ACT/007/013 File #5

LOCATION Emery County

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (*NPDES*)

DISCHARGE MONITORING REPORT (*DMR*)

Form Approved. OMB No. 2040-0004 Approval expires 9-30-85

(2-16) PERMIT NUMBER: UT-00-2920

(17-19) DISCHARGE NUMBER: 001

001, 002, 003a, 004, 005, 006, 007a, 007b, 007c, 008, 009a, 009b, 009c, 010.

MONITORING PERIOD

	YEAR	MO	DAY		YEAR	MO	DAY
FROM				TO			
	(20-21)	(22-23)	(24-25)		(26 27)	(28-29)	(30-31)

NOTE: Read instructions before completing this form.

PARAMETER (32-37)		(3 Card Only) QUANTITY OR LOADING (46-53) AVERAGE	(54-61) MAXIMUM	UNITS	(4 Card Only) QUALITY OR CONCENTRATION (38-45) MINIMUM	(46-53) AVERAGE	(54-61) MAXIMUM	UNITS	NO. EX (62-63)	FREQUENCY OF ANALYSIS (64-68)	SAMPLE TYPE (69-70)
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										
	SAMPLE MEASUREMENT										
	PERMIT REQUIREMENT										

RECEIVED APR 12 1990 DIVISION OF OIL, GAS & MINING

NAME/TITLE PRINCIPAL EXECUTIVE OFFICER		TELEPHONE		DATE		
John Palfy, Agent for Kaiser	I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN, AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 USC § 1001 AND 33 USC § 1319 (*Penalties under these statutes may include fines up to $10,000 and/or maximum imprisonment of between 6 months and 5 years.*)	SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR AUTHORIZED AGENT	AREA CODE 505	NUMBER 445-2351	YEAR 1990	MO 4	DAY 10
TYPED OR PRINTED						

COMMENT AND EXPLANATION OF ANY VIOLATIONS (*Reference all attachments here*)

No discharge occurred from any of the NPDES discharge points listed above.

EPA Form 3320-1 (Rev. 10-79) PREVIOUS EDITION TO BE USED UNTIL SUPPLY IS EXHAUSTED (REPLACES EPA FORM T-40 WHICH MAY NOT BE USED.)

GENERAL INSTRUCTIONS

1. If form has been partially completed by preprinting, disregard instructions directed to entry of that information and proceed
2. Enter "PERMITTEE NAME/MAILING ADDRESS" (and facility name/location if different) "PERMIT NUMBER" and
"OUTFALL NUMBER" where indicated. (A separate form is required for each discharge.)
3. Enter dates beginning and ending "MONITORING PERIOD" covered by form where indicated.
4. Enter each "PARAMETER" as specified in monitoring requirements of permit.
5. Enter "SAMPLE MEASUREMENT" data for each parameter under "QUANTITY" and "QUALITY" in units specified in permit.
Under "AVERAGE" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements taken during "MONITORING PERIOD." "MAXIMUM" and "MINIMUM" are normally extreme high and low measurements obtained during "MONITORING PERIOD." (NOTE to municipals with secondary treatment requirement: enter 7-day average measurement under "AVERAGE" and maximum 7-day average of sample measurements obtained during "MONITORING PERIOD" under "MAXIMUM".)
6. Enter "PERMIT REQUIREMENT" for each parameter under "QUANTITY" and "QUALITY" as specified in permit.
7. Under "NO. EX" enter number of sample measurements during monitoring period that exceed maximum (or fall below minimum) permit requirement for "QUALITY" average as appropriate) permit requirement for each parameter. If none, enter "0".
8. Enter "FREQUENCY OF ANALYSIS" both as "SAMPLE MEASUREMENT" (actual frequency of sampling and analysis during monitoring period) and as "PERMIT REQUIREMENT" specified in permit. (e.g. Enter "CONT" for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
9. Enter "SAMPLE TYPE" both as "SAMPLE MEASUREMENT" (actual sample type used during monitoring period) and as "PERMIT REQUIREMENT." (e.g. Enter "GRAB" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)

(FOLD HERE FIRST)

10. WHERE VIOLATIONS OF PERMIT REQUIREMENTS ARE REPORTED, ATTACH A BRIEF EXPLANATION TO DESCRIBE CAUSE AND CORRECTIVE ACTIONS TAKEN. REFERENCE EACH VIOLATION BY DATE.
11. If "no discharge" occurs during monitoring period, enter "NO DISCHARGE" across form in place of data entry.
12. Enter "NAME/TITLE OF PRINCIPAL EXECUTIVE OFFICER" with "SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR AUTHORIZED AGENT," "TELEPHONE NUMBER" and "DATE" at bottom of form.
13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
14. More detailed instructions for use of this DISCHARGE MONITORING REPORT (DMR) form may be obtained from Office(s) specified in permit.

LEGAL NOTICE

This report is required by law (33 U.S.C. 1318; 40 C.F.R. 125.27). Failure to report or failure to report truthfully can result in civil penalties not to exceed $10,000 per day of violation; or in criminal penalties not to exceed $25,000 per day of violation, or by imprisonment for not more than one year, or by both.

FOLD HERE SECOND

FOLD HERE THIRD

STAPLE HERE