0001

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/007/017

Inspection Date 12/9/87

Permittee/Operator Name Beaver Creek Coal Company

Business Address P.O. Box 1378

City Price State Utah Zip 84501

Mine Gordon Creek 3 & 6 ☐ Surface ☒ Underground ☐ Other

County Carbon State Utah

Company Official(s) Jay Marshall

State Official(s) Jim Stiche

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 11:00 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 10/22/87 Weather conditions Clear 35°F

Acreage 668 ☒ Permitted 34.4 ☒ Disturbed 7.5 ☒ Regraded 28 ☒ Seeded 28 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☐	☐	☐	☐
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☒	☐	☐	☒
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/007/017

Inspection Date 12/9/87

Please number comments to correspond with topics on previous page.

4c. Water monitoring data for the 3rd quarter was examined. All stations were dry, resulting in no data.

4d. The silt fence installation on the east side of the access road (just below the sediment ponds) requires minor maintenance. The mine site has a 6 inch covering of snow and the ground is frozen. The operator will perform the required maintenance on the silt fence when the weather will allow.

Copy of report mailed to ~~D. Griffin (OSM)~~ Brian Smith OSM + Dan Guy (BCCC)

Copy of report given to J. Helfrich + J. Whitehead

Inspector's signature Jim Fricke 12/9/87 No. 22

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE