0002

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Jch JM

inspection report

Permit No. ACT/007/016

Inspection Date 12/7/87

Permittee/Operator Name Beaver Creek Coal Co.

Business Address P.O. Box 1378

City Price, State UT Zip 84501

Mine Gordon Creek 2&7 ☐ Surface ☒ Underground ☐ Other

County Carbon State

Company Official(s) DAN GUY

State Official(s) BILL MALENCIK, BRENT STETTLER

Time of inspection 8:00 ☒ a.m. ☐ p.m. to 11:00 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 11/9-13/87 Weather conditions SNOWING/Snow Covered Site

Acreage 2289 ☐ Permitted 9 ☐ Disturbed — ☐ Regraded — ☐ Seeded 9 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☒
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/016

Inspection Date 12/7/87

Please number comments to correspond with topics on previous page.

General Observations. The mine site was snow covered. It was snowing during the inspection with about 2" of new snow cover. No significant runoff was observed.

Permit. Mid Term Deficiencies dated 5/28/87 were reviewed together with BCCC responses. This review of the records revealed that responses had been made, but all issues cited in the 5/28/87 listing have not been finalized. BCCC is awaiting further action by DOGM/SLC.

Perimeter Markers. Additional markers have been installed since the undersigned made his last inspection. Markers were visible around the exterior boundary of the disturbed area.

Slides & Other Damage. A fault on a highwall north of the portal continues to seep water and small rocks & debris are caught by a berm (water) & chain link fence (rocks). This is an area that BCCC keeps a close eye on in order assure that safety

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/016

Inspection Date 12/7/87

Please number comments to correspond with topics on previous page.

conditions and the seep is draining along a berm and into a culvert thence to Sed Pond #2

Roads Upper Gordon Creek was snow covered. The road above the gate was slick & trucks were starting to stack up. If things didnt get better BCCC was going to some abrasive material on the road for improved traction.

Copy of report mailed to Dan Guy, BCCC; SLC For Brian Smith OSM; Joe Helfrich DOGM

Copy of report ~~given to~~ filed PFO.

Inspector's signature Tim J Dmalnick No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE