0008

File Gch 10-13-87

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/016

Inspection Date 10/1/87

Permittee/Operator Name Beaver Creek Coal Co.

Business Address P.O. Box 1378

City Price State Ut. Zip 84501

Mine Gordon Creek 2&7 ☐ Surface ☒ Underground ☐ Other

County Carbon State Ut.

Company Official(s) None Available/Hunting Vacation

State Official(s) Bill Malencik & Harold Sandbeck

Time of inspection 1 : ___ ☐ a.m. ☒ p.m. to 5 : 30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 9/3/87 Weather conditions Clear/Dry/Warm

Acreage 2289 ☑ Permitted 9 ☑ Disturbed — ☐ Regraded — ☐ Seeded 9 ☑ Bonded

Enforcement Action None

Maintenance Consideration: 1/2 round culvert

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☒	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☒
— Diversions	☐	☒	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☒	☐	☐
— Surface and groundwater monitoring	☐	☒	☐	☐
— Effluent limitations	☐	☒	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☒	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☒	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☐	☒	☐	☐
14. Subsidence control	☐	☒	☐	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
— Construction	☐	☒	☐	☐
— Drainage controls	☒	☐	☐	☒
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☒	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. _____

Inspection Date _____

Please number comments to correspond with topics on previous page.

General. Beaver Creek regular work schedule is 10 hrs/day four days a week, monday thru thursday. All workers were off for a long weekend to accomodate hunters except for the receptionist & the security guard. Telephoned the receptionist and checked in with the security guard. The environmental staff was on vacation thursday 10/1/87.

No serious problems were encountered on this inspection. In fact the mine site looked good and a few items are mentioned herein for only as possible preventative maintenance items for Beaver Creeks consideration. The thought being that some routine maintenance at this time with the favorable weather conditions may be easier to handle than at a later date.

STREAM CHANNEL DIVERSIONS: The 1/2 round 24 inch culvert by the upper sediment pond even though it has been reported as being self cleaning and shows no current potential for overflow, has some small areas of localized sediment buildup that the company may wish to clean.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. _____

Inspection Date _____

Please number comments to correspond with topics on previous page.

Sediment Ponds: All sediment ponds contained water and were not discharging.

Road/Maintenance & Drainage Control. The main haul road from the gate to coal stockpile was recently maintained. The drainage ditches on both sides of the road were cleaned & sloped with new straw bales installed for sediment control.

Copy of report mailed to Joe Helfrich, DOGM, Brian Smith, OSM.

Copy of report given to Dan Guy, BCCC/Hand delivered 10/5/87

Inspector's signature Wm. J. Malenick No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE