0010

File

Job

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/016
Inspection Date 9/3/87

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State Ut. Zip 84501
Mine Gordon Creek 2 & 7 ☐ Surface ☒ Underground ☐ Other
County Carbon State
Company Official(s) Dan Guy
State Official(s) Wm. J Malencik
Time of inspection 1:00 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 7/13/87 Weather conditions Clear/Cool
Acreage 2289 ☑ Permitted 9 ☑ Disturbed — ☐ Regraded — ☐ Seeded 9 ☑ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
a – Stream channel diversions	☒	☐	☐	☒
b – Diversions	☐	☐	☐	☐
c – Sediment ponds and impoundments	☒	☐	☐	☒
d – Other sediment control measures	☐	☐	☐	☐
e – Surface and groundwater monitoring	☐	☐	☐	☐
f – Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a – Construction	☐	☐	☐	☐
b – Drainage controls	☒	☐	☐	☒
c – Surfacing	☐	☐	☐	☐
d – Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/016

Inspection Date 9/3/87

Please number comments to correspond with topics on previous page.

2- Signs: New safety signs had been installed recently. This was done in connection with deletion of a portion of the mine access/haul road at the lower end of the mine site.

3. Topsoil: Topsoil piles contained a good vegetal cover and were adequately protected.

4a. Stream Channel Diversions. Were checked and were in conformance with the MRP.

4c Sediment Pond, Contained water and was not discharging at the time of inspection.

16b Road-Drainage Control. Drainage ditches on both sides of the haul road had recently been cleaned, reshaped, and new strawbales installed for sediment control.

Copy of report mailed to Dan Guy, BCCC; Brian Smith OSM.

Copy of report given to Joe Helfrich - DOGM.

Inspector's signature Tom J. Malencik No. 26

9/8/87

WHITE → DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE