0028

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. Act/007/016

Inspection Date 2/8/88

Permittee/Operator Name Beaver Creek Coal Co.

Business Address P.O. Box 1378

City Price State Ut. Zip

Mine Gordon Creek 2 & 7 ☐ Surface ☒ Underground ☐ Other

County Carbon State

Company Official(s) Dan Guy

State Official(s) Dan Duce, Rick Smith

Time of inspection 3:00 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 1-6 and 7-88 Weather conditions Clear and cool

Acreage 2289 ☒ Permitted 9 ☒ Disturbed ☐ Regraded ☐ Seeded 9 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a – Stream channel diversions	☐	☐	☐	☐
b – Diversions	☒	☐	☐	☒
c – Sediment ponds and impoundments	☒	☐	☐	☒
d – Other sediment control measures	☐	☐	☐	☐
e – Surface and groundwater monitoring	☐	☐	☐	☐
f – Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a – Construction	☐	☐	☐	☐
b – Drainage controls	☒	☐	☐	☐
c – Surfacing	☒	☐	☐	☒
– Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act 1007 1016

Inspection Date 2/8 1888

Please number comments to correspond with topics on previous page.

General Comments: The mine site was still covered with snow, runoff was minimal.

4b) Diversions.

At the time of the inspection Diversions were functioning to divert runoff to sediment ponds. All Diversions will Need to be monitored closely during snow melt to ensure proper ranoff control.

4C) Sediment ponds and impoundments.

The small impoundment by the fuel storage area and the highwall Next to the office, was full of ice and oil. Mr Guy said this impoundment is pumped off by an oil recycler when full. This impoundment should be pumped soon.

16c Roads: Surfacing

The road Just below the mine site was slick, requireing a few empty coal trucks to be pushed up to the site by loaders.

Copy of report mailed to Dan Guy, BCCC, Brian Smith, OSM

Copy of report given to John Whitehead Joe Helfrich

Inspector's signature Dan Dunn 2/17/88 No. 11

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE