0014

gdh pgl

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/016

Inspection Date Aug. 22, 1990

Permittee/Operator Name Beaver Creek Coal Company

Business Address P.O. Box 1378

City Price State UT Zip 84501

Mine Gordon Creek 2, 7, & 8 ☐ Surface ☒ Underground ☐ Other

County Carbon State UT

Company Official(s) Mel Conrod

State Official(s) Bill Malemik, Susan White

Time of inspection 7:00 ☒ a.m. ☐ p.m. to 12:30 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection 7/5/90 Weather conditions Clear and fair

Acreage 228 ☐ Permitted 18 ☐ Disturbed ☐ Regraded ☐ Seeded 18 ☐ Bonded

Enforcement Action None, maintance items suggested

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☑	☐	☐	☑
2. Signs and markers	☑	☐	☐	☑
3. Topsoil	☑	☐	☐	☑
4. Hydrologic balance				
a – Stream channel diversions	☑	☐	☐	☐
b – Diversions	☑	☐	☐	☑
c – Sediment ponds and impoundments	☑	☐	☐	☑
d – Other sediment control measures	☑	☐	☐	☐
e – Surface and groundwater monitoring	☑	☐	☐	☐
f – Effluent limitations	☑	☐	☐	☑
5. Explosives	☑	☐	☐	☐
6. Development waste and spoil disposal	☑	☐	☐	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☑	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☑	☐	☐	☐
10. Slides and other damage	☑	☐	☐	☐
11. Contemporaneous reclamation	☑	☐	☐	☑
12. Backfilling and grading	☑	☐	☐	☐
13. Revegetation	☑	☐	☐	☐
14. Subsidence control	☑	☐	☐	☐
15. Cessation of operations	☑	☐	☒	☑
16. Roads				
– Construction	☑	☐	☐	☐
– Drainage controls	☑	☐	☐	☐
– Surfacing	☑	☐	☐	☐
– Maintenance	☑	☐	☐	☐
17. Other transportation facilities	☑	☐	☐	☐
18. Support facilities and utility installations	☑	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT 007/016

Inspection Date 8/22/90

Please number comments to correspond with topics on previous page.

1. All records were reviewed and found to be in order. The UPDES, permit # UT60004 coverage began 6/1/89. The Reclamation Bond issued by United Pacific Insurance Co., U-629965, was effective 7/30/87 until bond release. The SPCC report was updated on 3/90.

2. All required signs and markers were present. It was suggested to the operator to look over the entire disturbed area and place disturbed area markers in their appropiate places, especially at Mine #8 and Sweets Pond. The Topsoil Storage Sign should be installed better than it is. The Sweets Pond need an additional 2 Stream Buffer Zone Signs

3. The berm around the Sweets Topsoil pile ~~[illegible]~~ while fully functional should have a little hand work done.

4. b. While all dimensions were functional a few will soon need some maintance, these are: the ditch behind the water tank on #2 pad; berm on NE corner of #8 pad; the culvert ~~at~~ along the road at bend into #8 pad; the drainage for #7 pad under the belt line should be redefined; clean out culvert sump at end of half

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT 007/014

Inspection Date

Please number comments to correspond with topics on previous page.

sound at #2 mine; and redefine haulroad ditch along southside of loop and behind bath house

4 C.f. no discharge was reported for the sediment ponds during the 2nd quarter. The as-builts of the sediment ponds were certified by an engineer. A head cut is begining on an inlet to the Sweets pond, this should be corrected. Sediment Ponds were clean and contained some water.

15. The operator has commented that all ~~co~~ recoverable coal should be removed from #8 mine in October. Reclamation of the entire site may begin in 1991.

11. The revegetation preformed in fall 1989 around #8 mine looked in good condition.

Copy of report mailed to John Kathman (OSM), Dan Guy (BCC)

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature Susan M. White No. 35

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

an equal opportunity employer