0004

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. Act. 007/006

Inspection Date Nov. 24, 1992

Permittee/Operator Name Mountain Coal Company.

Business Address P.O. Box 1378

City Price State Ut Zip 84501

Mine Gordon Creek 2, 7 & 8 ☐ Surface ☒ Underground ☐ Other

County Carbon State Ut

Company Official(s) Dan Guy

State Official(s) Bill Malencik

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 11:30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 10-29-92 Weather conditions Mine Site Snow Covered/Clear.

Acreage 2289 ☐ Permitted 17² ☐ Disturbed ☐ Regraded ☐ Seeded 17² ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐

	YES	NO	N/A	COMMENTS
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☒	☐	☐	☒
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act 007/006

Inspection Date Nov. 24, 1992

Please number comments to correspond with topics on previous page.

General Comments. The mine site was covered with snow. The snow depth varied but the minimum depth was nine inches. The operator contractor has started backfilling and grading on the lower site in the vicinity of the office and coal storage area.

Signs & Markers. Required signs and markers were observed. The ID signs were displayed by the lower impoundment (truck water loadout out area) and the mine gate.

Sediment Pond. The snow was not melting and no runoff was entering or being discharged from the sediment pond.

Road. Since the mine is not operational and in the reclamation mode, the operator is not removing snow from the mine roads.

The operator replaced drainage control devices in the haul road ditch between the middle impoundment and the mine gate.

Support Facilities. The mine gate is locked at all times. The mine site is accessible by foot; however, if vehicle access is needed it will be necessary for responsible officials to contact Dan Guy.

Copy of report mailed to MCC/Dan Guy; OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature Wm. J. Malenick No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE