1-9-89
7080

0001

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/007/017

Inspection Date Jan 4, 1989

Permittee/Operator Name Beaver Creek Coal Co.

Business Address P.O. Box 1378

City Price State Ut Zip 84501

Mine Garden Creek 3&6 ☐ Surface ☒ Underground ☐ Other

County Carbon State Ut

Company Official(s) Dan Guy

State Official(s) Bill Malenak, John Whitehead

Time of inspection 1:00 ☐ a.m. ☒ p.m. to ___:___ ☐ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 12/7/88 Weather conditions Cloudy/Cold

Acreage 668 ☐ Permitted 34 ☐ Disturbed 28 ☐ Regraded 28 ☐ Seeded 28 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☒	☐	☐	☒
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

DOGM/IR-1

an equal opportunity employer

11/86 001049

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/007/017

Inspection Date 1/4/89

Please number comments to correspond with topics on previous page.

General Comments A partial inspection report was conducted. The first portion was a records review. The second and final portion was a field check[a]

RECORDS - The following records were reviewed:

Sediment Pond Pond inspection reports was completed on 10/26/88. The report showed the pond to be dry and no problems noted.

Water Monitoring Water monitoring records were reviewed and reports dated as follows for the three stations:

Station	Location	Description	Frequency	1988 Record Dates
3-1-W	Pond Inflow	Eph St.	Q	3/22, 5/18, 9/19, 11/23
3-2-W	" Disch.	NPDES	M	9/19, 10/26, 11/23, 12/11*
3-4-W	Coal Cyn	Eph. St	Q	3/22, 5/18, 9/19 11/23

* Previous reports showed the station had been monitored each month in C.Y. 88

No problems noted.

Subsidence - Subsidence record for 1988 was part of the mine record. The contract survey was completed by R&W Surveying of Price, Utah. Six stations were surveyed. Station 6 showed the greatest displacement of +.2 of a foot.

a/ Snowpack prevented the group to access the mine site

Copy of report mailed to • ~~Beaver Creek Coal Co.~~ Dan Guy.

Copy of ~~report given~~ field to • SLC For: OSM/Brian Smith; DOGM/Joe Helfrich

• PFO

Inspector's signature Jim J. Smalenak No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2 1/4/89

an equal opportunity employer

11/86 001049