6-6-89 0004

7080

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

RCS

inspection report

Permit No. INA/007/017

Inspection Date May 24, 1989

Permittee/Operator Name Beaver Creek Coal Co.

Business Address P.O. Box 1348

City Price State Ut Zip 84501

Mine Gordon Creek 3&6 ☐ Surface ☒ Underground ☐ Other

County Carbon State

Company Official(s) Dan Guy.

State Official(s) Bill Malencik

Time of inspection 7:30 ☒ a.m. ☐ p.m. to 3:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection 4/14/89 Weather conditions Clear/Windy/Cool

Acreage 668 ☐ Permitted 34.4 ☐ Disturbed 28 ☐ Regraded 28 ☐ Seeded 28 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☒
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☐	☐	☒	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/007/017

Inspection Date 5/24/89

~~Please number~~ comments to correspond with topics on previous page.

Permit: A review of DOGM & the operators records relative to the permit shows no significant action and/or issues. The only recent item noted in the operators file is correspondence from the Dept of Health dated 5/1/89 wherein the operator was notified UPDES permit # UT 0023060 for Garden Creek No 3 & 6 mines will be inactivated because the mine site has been reclaimed.

Stream Channel Diversion: Stream diversion was checked and it appears no runoff took place since the last inspection. Diversions fully functional.

Diversions: Most of the diversions were observed at key points. All were functional and no problems noted.

Sediment Pond: Sediment pond was stable, dry and showed no evidence of discharge since the last inspection. Sediment matter was in place and pond does not require clean out. As for operator records, certification was checked and dated 9/1/88; inspection & reports were of record and dated 1/24/89 and 3/14/89.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/007/017

Inspection Date 5/24/89

Please number comments to correspond with topics on previous page.

(Other Sediment Control): Silt fences and dugout pond were checked. All are functional. The operator installed additional silt fences adjacent to existing silt fences where the silt fence fabric appeared to start to deteriorate.

(Water Monitoring): Water monitoring requirements were met by the Operator with results as follows (1st quarter):

3-1-W, Coal Cyn (Above), Stream, sampled 3/14/89, DRY

3-2-W, Sed Pond (Discharge) inaccessible 1/24 & 2/28/89; 3/14/89 & 4/17/89.

3-4-W, Coal Cyn (Below), Stream, sampled 3/14/89, Dry

(Revegetation): Recent rains & snows that have hit the mine site have been most beneficial to the vegetation in two ways, ie, (1) sustaining seeded/planted/established vegetation and (2) Seeds from last fall established vegetation, primarily grass, have germinated and are most abundant in the track depressions made this spring by deer & elk when soil conditions were very moist.

Other: Annual report submitted 3/31/89 to DOGM which covered all salient information, including the subsidence report of 10/9/88, was on file and reviewed by the undersigned.

Copy of report mailed to SLC: FOR-OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report given to Beaver Creek Coal Co/Dan Guy

" " " filed PFO

Inspector's signature Tom J. Malencik No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

5/24/89

DOGM/IR-2

an equal opportunity employer

11/86 001049