0003

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/007/017

Inspection Date 3/13-16/90

Permittee/Operator Name Beaver Creek Coal Company.

Business Address P.O. Box 1378

City Price State Ut Zip 84501

Mine Gordon Creek 3&6 ☐ Surface ☒ Underground ☐ Other

County Carbon State Ut

Company Official(s) Dan Guy

State Official(s) Bill Malencik

Time of inspection 8:00 ☒ a.m. ☐ p.m. to 10:00 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete*

Date of last inspection 2/22/90 Weather conditions Cold/Snowing/Blowing

Acreage 668 ☒ Permitted 34 ☐ Disturbed 28 ☐ Regraded 28 ☐ Seeded 28 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/007/017

Inspection Date 3/13-16/90

Please number comments to correspond with topics on previous page.

General Comments The weather conditions were not conducive to conducting a field inspection. The snow was drifted by the gate and aided by a fast approach we got through the gate. However the mine area where the lower treatment starts was covered with deep drifted snow. Suffice it to say we shoveled our way out so the vehicle could get traction. The afternoon of the 16th walked from the gate to the sediment ponds.

Signs & Markers: I.D sign was in place at the gate. Disturbed markers were observed from the gate to the sediment pond.

Sediment Pond. lower cell did not contain water, however, was snow covered. Upper cell appeared to contain a small amount of runoff (frozen).

Pond inspection report was completed by the operator and dated 2/12/90. Pond as built certification was stamped, signed and dated 9/1/88

Roads. The main access to the road site was covered with snow. Road certification on file and dated 3/1/90

Copy of report mailed to { BCCC/Dan Guy. SLC For: OSM/Brian Smith, DOGM Joe Helfrich

Copy of report ~~given~~ filed to PFO

Inspector's signature [signature] No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

3/19/90

DOGM/IR-2

an equal opportunity employer

11/86 001049