0010

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gd pg

inspection report

Permit No. ACT/007/017
Inspection Date 8/22/90

Permittee/Operator Name Beaver Creek Coal Company
Business Address P.O. Box 1378
City Price State UT Zip 84501
Mine Gordon Creek 3&6 ☐ Surface ☒ Underground ☐ Other
County Carbon State UT
Company Official(s) Mel Conrad
State Official(s) Bill Malencik & Susan White
Time of inspection 12:30 ☐ a.m. ☒ p.m. to 1:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 7/5/90 Weather conditions Fair & Warm
Acreage 668 ☐ Permitted 34 ☐ Disturbed 28 ☐ Regraded 28 ☐ Seeded 28 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☑	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☑	☐	☐	☐
— Diversions	☑	☐	☐	☐
— Sediment ponds and impoundments	☑	☐	☐	☑
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☑	☐	☐	☑
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/017

Inspection Date 8/22/90

Please number comments to correspond with topics on previous page.

13. Overall the revegetation was in very good condition. Evidence of sheep grazing was apparent, very few seed head remained on the grasses. The Operator has installed fences to prevent the sheep from grazing on the reclaimed area. A fence with gates allow the sheep access through the property along the road.

Thistles were checked and determinded not to be of the noxious type. Reference areas were marked and flagged.

4. The upper cell of the sediment pond contained some water. Ponds looked clean and stable.

Copy of report mailed to Dan Guy, BCCC; OSM, Brian Smith

Copy of report given to Joe Helfrich, DOGM

Inspector's signature Susan M. White No. 35

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE