0012

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. Act/007/017
Inspection Date 2/17/93

Permittee/Operator Name Mountain Coal Company
Business Address P.O. Box 591
City Somerset State Colo Zip 81434
Mine Gordon Creek 3&6 ☐ Surface ☒ Underground ☐ Other
County Carbon State Ut
Company Official(s) Dan Guy (Consultant)
State Official(s) Bill Malerlick
Time of inspection 9:00 ☐ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 1/14/93 Weather conditions Snowing
Acreage 668 ☐ Permitted 28 ☐ Disturbed 8 ☐ Regraded 28 ☐ Seeded 28 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act/007/017

Inspection Date 2/17/93

Please number comments to correspond with topics on previous page.

General Comments. The mine site and turnoff to the mine site was inaccessible because of snow and road conditions. Three feet of snow, compacted in places by melting and/or drifting, made the mine site difficult to reach without snow transportation which is not available. Furthermore, the mine is reclaimed and the snow conditions would have made it impossible to evaluate any of the environmental control measures.

Records. In light of the adverse field conditions reviewed the permit and allied records. No first quarter "93" reports were on hand at the designated office, nor are such records due until the end of the first quarter of 1993. All required records were on file.

Signs & Markers. The operator's representative stated he has the new I.D signs and when travel conditions are better he will be installing the new sign.

Copy of report mailed to MCC/K Welt; OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report given to Filed PFO

Inspector's signature [signature] No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

2/24/93

DOGM/IR-2

an equal opportunity employer

11/86 001049