File #6 ACT 007/018

0076

SC3 SOLDIER CREEK COAL CO.

Telephone (801) 637-6360

P.O. Box I
Price, Utah 84501

RECEIVED
JAN 07 1991
DIVISION OF
OIL, GAS & MINING

January 4, 1991

Daron R. Haddock
Permit Supervisor
Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, UT 84180-1203

RE: Certified Inspection Reports, Soldier Creek Coal Company
ACT/007/018 and ACT/007/034, Carbon County, Utah

Dear Daron:

Pursuant to R614-514.312, certified inspections and certified inspection statements are enclosed. The impoundments inspected and certified are as follows:

Soldier Canyon Mine - Sediment Pond
Soldier Canyon Mine - Sewage Lagoons
Banning Loadout - Sediment Pond

If you have any questions, please call.

Sincerely,

SOLDIER CREEK COAL COMPANY

Johnny Pappas

Johnny Pappas
Environmental Coordinator

JP/sm

SOLDIER CREEK COAL CO.

Telephone (801) 637-6360

P.O. Box I
Price, Utah 84501

QUARTERLY POND INSPECTION

Pond Being Inspected: Mine Sedimentation Pond

Date of Inspection: 12/11/90

Person(s) Making Inspection: J.T. Paluso

Any Structural Weakness, Erosion and Other Hazardous Conditions Noted: None

Any Routine Maintenance Required: None

Comments: Outlet gate works. Stream rip-rap looks good. We need to keep a lookout for rip-rap movement.

APPROVAL: Registered Professional Engineer No. 4028 THOMAS PALUSO State of Utah

DATE: 12/26/90

INSPECTION CERTIFICATION

I hereby certify that I am experienced in the construction of impoundments; I am qualified and authorized in the state of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been constructed and maintained in accordance with the approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Registered Professional Engineer
No. 4028
THOMAS
PALUSO
State of Utah

SOLDIER CREEK COAL CO.

Telephone (801) 637-6360

P.O. Box 1
Price, Utah 84501

QUARTERLY POND INSPECTION

Pond Being Inspected: Sewage Lagoon

Date of Inspection: 12/11/90

Person(s) Making Inspection: J.T. Paluso

Any Structural Weakness, Erosion and Other Hazardous Conditions Noted: None

Any Routine Maintenance Required: None

Comments: Weed control is good. Water level is approximately 18 inches from top of cell.

APPROVAL: Registered Professional Engineer No 4028 PALUCO State of Utah

DATE: 12/26/90

INSPECTION CERTIFICATION

I hereby certify that I am experienced in the construction of impoundments; I am qualified and authorized in the state of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been constructed and maintained in accordance with the approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Registered Professional Engineer
No. 4028
THOMAS PALUCO
State of Utah

SOLDIER CREEK COAL CO.

Telephone (801) 637-6360

P.O. Box 1
Price, Utah 84501

QUARTERLY POND INSPECTION

Pond Being Inspected: Banning Sedimentation Pond

Date of Inspection: 12/11/90

Person(s) Making Inspection: J.T. Paluso

Any Structural Weakness, Erosion and Other Hazardous Conditions Noted: None

Any Routine Maintenance Required: None

Comments: Small amount of erosion occuring on incised portion of pond. This erosion does not have an affect on the pond.

APPROVAL: Registered Professional Engineer No. 4028 PALUSO State of Utah

DATE: 12/26/90

INSPECTION CERTIFICATION

I hereby certify that I am experienced in the construction of impoundments; I am qualified and authorized in the state of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been constructed and maintained in accordance with the approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Registered Professional Engineer
No. 4023
THOMAS
PALUCO
State of Utah