6|5
7|8

1|6
12|7

Federal Lease U-010581

N 1° 00' E

N 2° 24' W

Federal Lease U-010581
Andalex Resources, Inc. Fee

1st East

Main North (active)

Main East

ACP Federal Lease SL-068444-00028

Andalex Resources, Inc. Fee
Federal Lease SL-027304 00

Federal Lease U-010581
Federal Lease SL-27304

12|7
13|18

Outcrop

Outcrop

Outcrop

Federal Lease SL-027304
Federal Lease SL-63058

7|8
18|17

1992
EXTRACTION

LEGEND

- 1992 Development Only
- 1992 Development & Pillars
- 1992 Development & Slab
- 1992 Pillars Only
- 1992 Slab Only

N

RECEIVED
APR 0 5 1993
DIVISION OF
OIL GAS & MINING

RECEIVED
MAR 3 1 1993
DIVISION OF OIL
GAS & MINING PRICE UTAH

I, Bruce F.B. Ware, do hereby certify that I am a registered land surveyor, that I hold certificate no. 4502, as prescribed by the state of Utah; that this survey was made by me and is true and correct as shown hereon.

ANDALEX
RESOURCES, INC.
Tower Division

Aberdeen Mine
P.O. Box 902
Price, Utah 84501

DATE: February 1, 1993

MSHA Mine I.D. 42-02028

Individual responsible for the information shown on this map.
Laine Adair, Chief Engineer
(801) 637-5385

Scale:
100' 0' 200' 400'