31 32
6
32
6 5
32 33
5
33
5 4
1 6
12 7
5 4
8 9
4 3
9 10
12 7
13 18
7 8
18 17
8 9
17 16
Federal Lease U-66060
Federal Lease U-010581
Andalex Resources, Inc. Fee
Zion Lease
Probable Rock Split
Probable Rock Split
Rock Split
Rock Split
Main East
4th North
2nd East
1st East
Roof
Adverse
Low Coal
Low Coal
Federal Lease U-010581
Federal Lease U-05067
Federal Lease U-05067
Federal Lease U-05067
Sunedco Lease Fee
Outcrop
Outcrop
Outcrop
Outcrop
Probable Burn Line
Burn
AEP Federal Lease SL048442-050115
Andalex Resources, Inc. Fee
Federal Lease SL-027304
Federal Lease U-010581
Federal Lease SL-027304
Federal Lease SL-063058
Federal Lease U-010581
Federal Lease U-010581 (M)
Federal Lease SL-027304
Federal Lease SL-063058
Federal Lease SL-063058 (M)
Federal Lease
U-05067 (M)
Sunedco Lease Fee
LEGEND
1994 Development Only
1994 Development & Pillars
1994 Slab Only
N
I, Bruce T.S. Ware, do hereby certify that I am a registered land surveyor, that I hold certificate no. 4502, as prescribed by the state of Utah; that this survey was made by me and is true and correct as shown hereon.
DATE: January 13, 1995
MSHA Mine I.D. 42-01750
Individual responsible for the information shown on this map.
Laine Adair, Chief Engineer
(801) 637-5385
ANDALEX
RESOURCES, INC.
Tower Division
Apex Mine
Sunnyside Seam
P.O. Box 902
Price, Utah 84501
Scale:
200' 0' 400' 800'