0004

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah
801-538-5340

Partial: XX Complete: ___ Exploration ____
Inspection Date & Time: November 9, 1992/02:00pm-03:00pm
Date of Last Inspection: October 15, 1992

Mine Name: Blazon #1 Mine County: Carbon Permit Number: ACT/007/021
Permittee and/or Operator's Name: None
Business Address: _____
Type of Mining Activity: Underground XX Surface ____ Prep. Plant ____ Other ____
Officials(s): State: Stephen J. Demczak Company: None
Federal Official(s): _____ Weather Conditions: 6"Snow/Cold
Existing Acreage: Permitted-320 Disturbed-4.5 Regraded-2.5 Seeded-2.5 Bonded-2.5
Increased/Decreased: Permitted-____ Disturbed-__ Regraded-__ Seeded-__ Bonded-____
Status: ___ Exploration/ ___ Active/ ___ Inactive/ __ Temp Cessation/ XX Bond Forfeiture
Reclamation (__ Phase I/ __ Phase II/ __ Final Bond Release/ __ Liability ____ Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[ ]	[ ]	[ ]	[ ]
2. SIGNS AND MARKERS	[ ]	[ ]	[ ]	[ ]
3. TOPSOIL	[ ]	[ ]	[ ]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[XX]	[ ]	[XX]	[ ]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
c. OTHER SEDIMENT CONTROL MEASURES	[XX]	[ ]	[XX]	[ ]
d. WATER MONITORING	[ ]	[ ]	[ ]	[ ]
e. EFFLUENT LIMITATIONS	[ ]	[ ]	[ ]	[ ]
5. EXPLOSIVES	[ ]	[ ]	[ ]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	[ ]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
8. NONCOAL WASTE	[ ]	[ ]	[ ]	[ ]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[ ]	[ ]	[ ]	[ ]
10. SLIDES AND OTHER DAMAGE	[ ]	[ ]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[ ]	[ ]	[ ]	[ ]
12. BACKFILLING AND GRADING	[ ]	[ ]	[ ]	[ ]
13. REVEGETATION	[ ]	[ ]	[ ]	[ ]
14. SUBSIDENCE CONTROL	[ ]	[ ]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[ ]	[ ]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[ ]	[ ]	[ ]	[ ]
b. DRAINAGE CONTROLS	[ ]	[ ]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[ ]	[ ]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[ ]	[ ]	[ ]	[ ]
19. AVS CHECK (4th Quarter-April, May, June)	[ ]	[ ]	[ ]	[ ]
20. AIR QUALITY PERMIT	[ ]	[ ]	[ ]	[ ]
21. BONDING & INSURANCE	[ ]	[ ]	[ ]	[ ]

INSPECTION REPORT
(Continuation sheet)

PERMIT NUMBER: ACT/007/021 DATE OF INSPECTION: November 9, 1992

(Comments are Numbered to Correspond with Topics Listed Above)

4a. Diversions -

The segment of diversions at the site have filled up with sediment and contain rocks from the hillsides. Thus maintenance is required for preventing erosion of the pad area.

Vandalism has taken place which involved in cutting down of chemical treated power poles. These poles are presently located in the stream channel which past through the center of the reclaim area. There may be a concern that these treated poles could create a problem with the water by adding unwanted chemical to the water that enters Scofield Reservoir.

4c. Other Sediment Control Measures -

Silt fences throughout the property are in need of repair. The majority of the fences are along the stream to filter out sediment.

**Snow has fallen and this will most likely be the last on site inspection until Spring.

Copy of this Report:

Mailed to:
Mailed to: Bernie Freeman (OSM)
Given to: Joe Helfrich (DOGM)
Filed to: Price Field Office
Date: December 2, 1992

Inspector's Signature and Number: Stephen J. Demczak #39
Stephen J. Demczak