0017

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

Partial: XX Complete: __ Exploration ____
Inspection Date/Time: January 31, 1994/04:00pm-04:30pm
Date of Last Inspection: December 14, 1993

Mine Name: Blazon #1 County: Carbon Permit Number: ACT/007/021
Permittee and/or Operator's Name: NAE (Insolvent), no known mailing address
Business: Mail cc attn: Steve Tanner, Route #1, Box 146G3, Helper, UT 84526 637-5986
Type of Mining Activity: Underground XX Surface ____ Prep. Plant ____ Other ____
Officials(s): State: Stephen J. Demczak Company: _____
Federal Officials: _____ Weather Conditions: Cold 2' snow
Existing Acreage: Permitted- 0 Disturbed- 4.5 Regraded- 2.5 Seeded- 2.5 Bonded- 0
Increased/Decreased: Permitted- ____ Disturbed- __ Regraded- __ Seeded- __ Bonded- ____
Status: ___ Exploration/ ___ Active/ ___ Inactive/ __ Temp Cessation/ XX Bond Forfeiture
Reclamation (__ Phase I/ __ Phase II/ __ Final Bond Release/ __ Liability _____ Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	[ ]	[XX]	[ ]
2. SIGNS AND MARKERS	[ ]	[ ]	[ ]	[ ]
3. TOPSOIL	[ ]	[ ]	[ ]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[ ]	[ ]	[ ]	[ ]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
c. OTHER SEDIMENT CONTROL MEASURES	[ ]	[ ]	[ ]	[ ]
d. WATER MONITORING	[ ]	[ ]	[ ]	[ ]
e. EFFLUENT LIMITATIONS	[ ]	[ ]	[ ]	[ ]
5. EXPLOSIVES	[ ]	[ ]	[ ]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	[ ]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
8. NONCOAL WASTE	[ ]	[ ]	[ ]	[ ]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[ ]	[ ]	[ ]	[ ]
10. SLIDES AND OTHER DAMAGE	[ ]	[ ]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[ ]	[ ]	[ ]	[ ]
12. BACKFILLING AND GRADING	[ ]	[ ]	[ ]	[ ]
13. REVEGETATION	[ ]	[ ]	[ ]	[ ]
14. SUBSIDENCE CONTROL	[ ]	[ ]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[ ]	[ ]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[ ]	[ ]	[ ]	[ ]
b. DRAINAGE CONTROLS	[ ]	[ ]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[ ]	[ ]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[ ]	[ ]	[ ]	[ ]
19. AVS CHECK (4th Quarter-April, May, June) _____ date	[ ]	[ ]	[ ]	[ ]
20. AIR QUALITY PERMIT	[ ]	[ ]	[ ]	[ ]
21. BONDING & INSURANCE	[ ]	[ ]	[ ]	[ ]

INSPECTION REPORT
(Continuation sheet)

PERMIT NUMBER: ACT/007/021 DATE OF INSPECTION: January 31, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

a) The Division, in the near future, will be designing a reclamation plan for Blazon. There is a possibility that the site will be reclaimed in 1994.

b) The preliminary estimate of the monies required to reclaim the site for use of wildlife and grazing may exceed $100,000. The forfeiture of the reclamation bond is for the amount of $38,000.

c) The North American Equities as an entity no longer exists. There is no agent for service for notice or regulatory action.

d) No additional information dealing with Blazon has been reported into the files recently.

The field inspection could not be taken due to inaccessibility to the site because of snow. The road had not been graded.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to:
Mailed to: Bernie Freeman (OSM)
Given to: Joe Helfrich (DOGM)
Filed to: Price Field Office
Date: February 4, 1994

Inspector's Signature and Number: Stephen J. Demczak #39
Stephen J. Demczak