0006

Document Information Form

Mine Number: C/007/022

File Name: Incoming

To: DOGM

From:

Person N/A

Company BEAVER CREEK COAL CO.

Date Sent: MAY 28, 1985

Explanation:

MINE SITE EVALUATION INSPECTION REPORT

cc:

File in:
C/007/022, 1985, Incoming
Refer to:
- ☐ **Confidential**
- ☐ **Shelf**
- ☐ **Expandable**

Date _____ For additional information

0006

RECEIVED

MAY 28 1985

DIVISION OF OIL GAS & MINING

007/022

United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report

For Office Use Only

1a (Y Y M M): 1 | 1b (Batch): | 1c (Report):

2. Name of Permittee: Beaver Creek Coal Co

3. Street Address: Po Box AV

4. City: Price | 5. State: UT

6. Zip Code: 84060 | 7. Area Code: 801 | 8. Telephone Number: 637-5050

9. MSHA Number: - -

10. Date of Inspection (Y Y M M D D): 850422

11. State Permit Number: ACT 007 022

12. Name of Mine:

13. County Code: 007 | 14. State Code: UT | 15. Strata: | 16. State Area Office: 01

17. OSM Field Office No.: 02 | 18. OSM Area Office No.: | 19. OSM Sample No.: | 20. Type of Inspection (Code): CFL | 21. Joint Inspection Yes: No: X | 22. Inspector's ID No.: 113

23. Status

A	02	Type of Permit
B	I	Mine Status (Code)
C	31	Type of Facility (Code)
D	00160.0	Number of Permitted Acres
E	00110.0	Number of Disturbed Acres

24. Type of Activity (check applicable boxes).

A	☐	Steep Slope	E	☐	Anthracite
B	☐	Mountain Top Removal	F	☐	Federal Lands
C	☐	Prime Farmlands	G	☐	Indian Lands
D	☒	Alluvial Valley Floors	H	☐	Other

25. Performance Standards (Codes)

Instructions: Indicate compliance code. For any standard marked 2 or 3 provide narrative to support this determination.

Standards That Limit the Effects to the Permit Area

A	3	Distance Prohibitions
B	1	Mining Within Permit Boundaries
C	1	Signs and Markers
D	1	Sediment Control Measures
E	1	Design and Certification Requirements—Sediment Control
F	1	Effluent Limits
G	1	Surface Water Monitoring
H	1	Ground Water Monitoring
I	3	Blasting Procedures
J	1	Haul/Access Road Design and Maintenance
K	3	Refuse Impoundments
L		Other: Specify

Standards That Assure Reclamation Quality and Timeliness

M	1	Topsoil Handling
N	3	Backfilling and Grading
O	1	Following Reclamation Schedule
P	1	Revegetation Requirements
Q	3	
R	1	
S	3	
T	3	
U	3	
V	1	
W		Other

File in:
☐ Confidential
☐ Shelf
☐ Expandable
Refer to Record No 0006 Date 5-28-85
In C/007/022, 1985, Incoming
For additional information

Distribution: Original - Field Office, Green - Headquarters, Blue - State's Copy, Yellow - Inspector's Copy, Pink - File Copy

*IE - 163 (1/83)

0006

RECEIVED

MAY 28 1985

DIVISION OF OIL GAS & MINING

007/022 #5

United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report

For Office Use Only

1a	1b	1c
Y Y M M	Batch	Report

2. Name of Permittee: Beaver Creek Coal Co

3. Street Address: Po Box AV

4. City: Price

5. State: UT

6. Zip Code: 84060

7. Area Code: 801

8. Telephone Number: 637-5050

9. MSHA Number: - -

10. Date of Inspection (Y Y M M D D): 850422

11. State Permit Number: ACT 007 022

12. Name of Mine:

13. County Code: 007

14. State Code: UT

15. Strata:

16. State Area Office: 01

17. OSM Field Office No.: 02

18. OSM Area Office No.:

19. OSM Sample No.:

20. Type of Inspection (Code): CFL

21. Joint Inspection Yes: No: X

22. Inspector's ID No.: 113

23. Status

A	02	Type of Permit
B	I	Mine Status (Code)
C	31	Type of Facility (Code)
D	00160.0	Number of Permitted Acres
E	00110.0	Number of Disturbed Acres

24. Type of Activity (check applicable boxes).

A		Steep Slope	E		Anthracite
B		Mountain Top Removal	F		Federal Lands
C		Prime Farmlands	G		Indian Lands
D	X	Alluvial Valley Floors	H		Other

25. Performance Standards (Codes)

Instructions: Indicate compliance code. For any standard marked 2 or 3 provide narrative to support this determination.

Standards That Limit the Effects to the Permit Area

A	3	Distance Prohibitions
B	1	Mining Within Permit Boundaries
C	1	Signs and Markers
D	1	Sediment Control Measures
E	1	Design and Certification Requirements—Sediment Control
F	1	Effluent Limits
G	1	Surface Water Monitoring
H	1	Ground Water Monitoring
I	3	Blasting Procedures
J	1	Haul/Access Road Design and Maintenance
K	3	Refuse Impoundments
L		Other: Specify

Standards That Assure Reclamation Quality and Timeliness

M	1	Topsoil Handling
N	3	Backfilling and Grading
O	1	Following Reclamation Schedule
P	1	Revegetation Requirements
Q	3	Disposal of Excess Spoil
R	1	Handling of Acid or Toxic Materials
S	3	Highwall Elimination
T	3	Downslope Spoil Disposal
U	3	Post Mining Land Use
V	1	Cessation of Operations: Temporary
W		Other

Distribution: Original - Field Office, Green - Headquarters, Blue - State's Copy, Yellow - Inspector's Copy, Pink - File Copy

IE - 163 (1/83)

United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report

007/022

26. State Permit Number 4 0 7 | 0 0 7 | 0 2 2

Copy Joe Hoffman

27. Date of Inspection (Y Y M M D D)

28. Yes ☐ No ☐ Do mining and reclamation activities on the site comply with the plans in the permit? If no, provide narrative to support this determination.

29. Indicate number of complete and partial inspections conducted by the State to date for this annual review period:

29a. 3 Number of Completes 29b. 7 Number of Partials

30. Indicate number of complete and partial inspections required by the State during this annual review period:

30a. 4 Number of Completes 30b. 8 Number of Partials

31. Has inspection frequency been met?

31a. Yes ☐ No ☒ Completes 31b. Yes ☐ No ☒ Partials

32. FEDERAL ENFORCEMENT INFORMATION. [Enter violation number. Check appropriate box(es)]

	Ten-Day Notice No.	Notice of Violation No.	Cessation Order No.	Violation Codes
A	☐	☐	☐	Authorizations to Operate
B	☐	☐	☐	Signs and Markers
C	☐	☐	☐	Backfilling and Grading
D	☐	☐	☐	Highwall Elimination
E	☐	☐	☐	Rills and Gullies
F	☐	☐	☐	Improper Fills
G	☐	☐	☐	Topsoil Handling
H	☐	☐	☐	Sediment Ponds
I	☐	☐	☐	Effluent Limits
J	☐	☐	☐	Water Monitoring
K	☐	☐	☐	Buffer Zones
L	☐	☐	☐	Roads
M	☐	☐	☐	Dams
N	☐	☐	☐	Blasting
O	☐	☐	☐	Revegetation
P	☐	☐	☐	Spoil on the Downslope
Q	☐	☐	☐	Mining Without Permit
R	☐	☐	☐	Exceeding Permit Limits
S	☐	☐	☐	Distance Prohibitions
T	☐	☐	☐	Toxic Materials
U	☐	☐	☐	Other Violations

33. Name of Authorized Representative *(print or type)* CHARLES BOTDORF #113

Signature of Authorized Representative Charles Botdorf Date 5/4/85

Signature of Reviewing Official [signature] Date 5/23/85

0006 5-23-85
007/022 15
01 5
11 0
03 0
02 0

Beaver Creek Coal Co.
P.O. Box AV
Price UT 84060

Mine Ca Spur Preparation Plant
Permit # ACT 007/022
Date: 4/22/85
Inspection Type Complete

Inspector C. Botdorf
Others Dan Guy, C.V. Spur

#1 Outstanding State Enforcement actions - none
Outstanding Federal Enforcement actions - none

#2 On April 22, 1985 a complete inspection of Castle Valley (C.V.) Spur Prep. Plant, Beaver Creek Coal was conducted. The preparation plant component of the facility is currently under temporary cessation. The operation performs as a load out facility. The prep plant by-pass, conveyor to stacking tubes is used to facilitate loading.

Mr. Burk Biersdorf, Plant Superintendent was at scale house. I conducted field review and was later joined by Mr Dan Guy, P.E. Mgr. of Permits and Compliance, Beaver Creek Coal

Haulroad, access, and work areas are well maintained and recent grading work of ditching is evident. All ponds and diversions and culverts were walked during the inspection. Culverts at the scale house and south of Sub Station should be better maintained. This was related to Mr Biersdorf. Photographs taken.

Pond #4 is full and Pond #6 (NPDES discharge point) does not appear to discharge. A backhoe was being used to clean out ditch between Ponds #4

and #6, The ditch and culvert were checked and gradient complications are suspitioned. Compliance is in progress and pond #4 will be discussed with the DOGM field representative Mr. Tom Wright, who is closely following the situation.

Topsoil and subsoil stockpiles are protected and have vegetative cover and markers. Perimeter markers of disturbed area are in place, and Mining i.d. ~~sign~~ sign is complete.

Waste material is controlled, refuse disposal planned.

Administrative review was conducted at Beaver Creek Coal Company offices:

Groundwater and surface water monitoring records were reviewed for wells CV 1 thru 13, and ditch CV-14 located NE of permit. Quarterly reports 3/8/84, 6/11/84, 9/14/84, and 12/14/84 reviewed. Report 3/19/85 has not yet been transmitted, was reviewed. NPDES Permit # OO239249, Art. outfall #002, no discharge unless bypass, etc. Part II A.5. DMRs 1st → 4th quarter reviewed.

The following documents and authorization were also available and included in the review:

#1 3/28/84 Intent of planning temporary cease of coal preparation operations at C.V. Spur.

7/17/84 Letter of certification of sediment ponds. Ponds have been constructed in accordance to the plan and design criteria.

7/26/84 Beaver Creek Coal accepts stipulations contained within the DOGM Final Technical Analysis and Decision Document for C.V. Spur.

8/6/84 Final Permit Approved C.V. Spur Prep Plant ACT 007 022.

9/4/84 EPA and Utah Health Department has established CMP spillway of Pond #6 as NPDES Outfall #001. Sediment pond #6 is required to have a total pond volume of 1795 acre ft. to accomodate a 10 yr/24 hr event.

Dan Gray P.E. of Beaver Creek Coal was most cooperative, and completeness and organization of administrative records is appreciated.

#3 Enforcement actions - none

#4 MSEIR

Code Standards

3 A, I, K, N, ~~O~~, S, T, U not applicable

This is a prep plant, loadout, refuse ~~bang~~ disposal area.

C. Bateman #113